


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 02.08.2024

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKG3193P**
MODEL : **MERCEDES C180**
DATE OF ACCIDENT : 02.08.2024
TIME OF ACCIDENT : 11:35 HOURS

WDD2040452A606207
Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Detid</i>	1	\$ 2,010.00	\$ 2,010.00
2	REAR BUMPER TOWING COVER <i>Len</i>	1	\$ 85.00	\$ 85.00
3	REAR BUMPER BOTTOM CENTER GARNISH <i>manidly could</i>	1	\$ 185.00	\$ 185.00
4	REAR BUMPER CORNER BRACKET <i>Len</i>	2	\$ 179.00	\$ 358.00
5	REAR BUMPER SIDE RETAINER <i>Len</i>	2	\$ 74.00	\$ 148.00
6	REAR BUMPER LOWER BRACKET (CENTER) <i>Len</i>	2	\$ 65.00	\$ 130.00
7	REAR BUMPER SIDE INNER GARNISH <i>Len</i>	1	\$ 285.00	\$ 285.00
8	REAR BUMPER CENTRE FRAME <i>Len</i>	1	\$ 342.00	\$ 342.00
9	REAR BUMPER REINFORCEMENT <i>Detid</i>	1	\$ 658.00	\$ 658.00
10	TAILLAMP <i>Len</i>	2	\$ 762.00	\$ 1,524.00
11	REAR FENDER DRAIN GARNISH <i>Len</i>	2	\$ 98.00	\$ 196.00
12	REAR FENDER COWLING <i>Len</i>	2	\$ 198.00	\$ 396.00
13	REAR FENDER INNER TRIM <i>Len</i>	2	\$ 425.00	\$ 850.00
14	BOOTLID <i>Detid</i>	1	\$ 2,450.00	\$ 2,450.00
15	BOOTLID CENTER MOULDING <i>new</i>	1	\$ 195.00	\$ 195.00
16	BOOTLID LOGO <i>Len</i>	1	\$ 64.00	\$ 64.00
17	BOOTLID EMBLEM 'C180' <i>Len</i>	1	\$ 86.00	\$ 86.00
18	BOOTLID EMBLEM 'KOMPRESSOR' <i>Len</i>	1	\$ 155.00	\$ 155.00
19	BOOTLID STOPPER <i>Len</i>	4	\$ 45.00	\$ 180.00
20	BOOTLID HINGE <i>Len</i>	2	\$ 131.00	\$ 262.00
21	BOOTLID INSULATOR <i>Len</i>	1	\$ 598.00	\$ 598.00

1540

90

762

1874

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKG3193P**
 MODEL : **MERCEDES C180**
 DATE OF ACCIDENT : 02.08.2024
 TIME OF ACCIDENT : 11:35 HOURS

22	BOOTLID TOP LOCK <i>new</i>	1	\$ 300.00	\$ 300.00	+
23	BOOTLID LOWER LOCK <i>new</i>	1	\$ 48.00	\$ 48.00	+
24	BOOTLID WEATHER STRIP <i>lit</i>	1	\$ 189.00	\$ 189.00	✓
25	BOOTLID NUMBER PLATE LAMP GARNISH <i>lit</i>	1	\$ 168.00	\$ 168.00	+
26	BOOTLID INNER HANDLE GARNISH <i>new</i>	1	\$ 128.00	\$ 128.00	+
27	REAR END PANEL <i>Repair</i>	1	\$ 1,460.00	\$ 1,460.00	+
28	REAR END PANEL INNER GARNISH <i>curled</i>	1	\$ 285.00	\$ 285.00	✓

5888

5299.20

TOTAL PRICE \$ 13,735.00
 LESS 10% \$ 1,373.50
SUB TOTAL PRICE \$ 12,361.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
3	REAR BUMPER BOTTOM CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	REAR BUMPER LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
5	BOOTLID SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
6	BOOTLID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
7	BOOTLID CENTER MOULDING CLIP <i>new</i>	1	\$ 50.00	\$ 50.00	+
8	BOOTLID NUMBER PLATE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
9	BOOTLID EMBLEM 'C&C' (SPECAIL TYPE) <i>new</i>	1	\$ 120.00	\$ 120.00	50
10	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
11	REAR FENDER DRAIN GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
12	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
13	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
14	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	+
15	REAR END PANEL INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
16	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	20

320

TOTAL \$ 1,320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	400

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKG3193P**
 MODEL : **MERCEDES C180**
 DATE OF ACCIDENT : 02.08.2024
 TIME OF ACCIDENT : 11:35 HOURS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	60
3	TUFF COAT	\$ 350.00	30
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	40
6	TRANFER BOOTLID MECHANISM	\$ 80.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
8	REMOVE AND REFIX AND RESET REVERSE SENSOR	\$ 250.00	50
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	X

TOTAL \$ 5,990.00

TOTAL PARTS COST : \$ 13,681.50
 TOTAL LABOUR COST : \$ 5,990.00
 TOTAL REPAIR COST : \$ 19,671.50

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Admin
 F/S 05/08/24.

04 days

total: 6829.20

L/S: 5450 ✓

1210