

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To In: _____ Vehicle No: _____

at W/O: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK63193P Yr Regn: 2011 / OCT

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 CD 1597

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 347132 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WD D2040452A606207

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. _____

05/08/24

HP Perfect

Date / Time

Action / Instruction

PELICCS

COE Expiry : 24/10/2031

Estimate given during : Yes C

1st Survey : No C

MV: 931K

PV: 33.6K

Nett: 59.4K

8576.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Invt (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

Report Format:

Report Format: _____

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 02.08.2024

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : SKG3193P
MODEL : MERCEDES C180
DATE OF ACCIDENT : 02.08.2024
TIME OF ACCIDENT : 11:35 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Detid</i>	1	\$ 2,010.00	\$ 2,010.00
2	REAR BUMPER TOWING COVER <i>Len</i>	1	\$ 85.00	\$ 85.00
3	REAR BUMPER BOTTOM CENTER GARNISH <i>Monedly cnd</i>	1	\$ 185.00	\$ 185.00
4	REAR BUMPER CORNER BRACKET <i>Detid</i>	2	\$ 179.00	\$ 358.00
5	REAR BUMPER SIDE RETAINER <i>Len</i>	2	\$ 74.00	\$ 148.00
6	REAR BUMPER LOWER BRACKET (CENTER) <i>Len</i>	2	\$ 65.00	\$ 130.00
7	REAR BUMPER SIDE INNER GARNISH <i>Len</i>	1	\$ 285.00	\$ 285.00
8	REAR BUMPER CENTRE FRAME <i>Len</i>	1	\$ 342.00	\$ 342.00
9	REAR BUMPER REINFORCEMENT <i>Detid</i>	1	\$ 658.00	\$ 658.00
10	TAILLAMP <i>Detid</i>	2	\$ 762.00	\$ 1,524.00
11	REAR FENDER DRAIN GARNISH <i>Detid</i>	2	\$ 98.00	\$ 196.00
12	REAR FENDER COWLING <i>Detid</i>	2	\$ 198.00	\$ 396.00
13	REAR FENDER INNER TRIM <i>Detid</i>	2	\$ 425.00	\$ 850.00
14	BOOTLID <i>Detid</i>	1	\$ 2,450.00	\$ 2,450.00
15	BOOTLID CENTER MOULDING <i>new</i>	1	\$ 195.00	\$ 195.00
16	BOOTLID LOGO <i>new</i>	1	\$ 64.00	\$ 64.00
17	BOOTLID EMBLEM 'C180' <i>new</i>	1	\$ 86.00	\$ 86.00
18	BOOTLID EMBLEM 'KOMPRESSOR' <i>new</i>	1	\$ 155.00	\$ 155.00
19	BOOTLID STOPPER <i>new</i>	4	\$ 45.00	\$ 180.00
20	BOOTLID HINGE <i>new</i>	2	\$ 131.00	\$ 262.00
21	BOOTLID INSULATOR <i>new</i>	1	\$ 598.00	\$ 598.00

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKG3193P**
 MODEL : **MERCEDES C180**
 DATE OF ACCIDENT : 02.08.2024
 TIME OF ACCIDENT : 11:35 HOURS

22	BOOTLID TOP LOCK <i>New</i>	1	\$ 300.00	\$ 300.00	+
23	BOOTLID LOWER LOCK <i>New</i>	1	\$ 48.00	\$ 48.00	+
24	BOOTLID WEATHER STRIP <i>lit</i>	1	\$ 189.00	\$ 189.00	✓
25	BOOTLID NUMBER PLATE LAMP GARNISH <i>lit</i>	1	\$ 168.00	\$ 168.00	+
26	BOOTLID INNER HANDLE GARNISH <i>New</i>	1	\$ 128.00	\$ 128.00	+
27	REAR END PANEL <i>Regr</i>	1	\$ 1,460.00	\$ 1,460.00	+
28	REAR END PANEL INNER GARNISH <i>Ambed</i>	1	\$ 285.00	\$ 285.00	✓

TOTAL PRICE \$ 13,735.00
 LESS 10% \$ 1,373.50
SUB TOTAL PRICE \$ 12,361.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	✓
3	REAR BUMPER BOTTOM CENTER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00	+
4	REAR BUMPER LOWER GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
5	BOOTLID SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00	+
6	BOOTLID INSULATOR CLIP (SET) <i>3 new</i>	1	\$ 50.00	\$ 50.00	+
7	BOOTLID CENTER MOULDING CLIP <i>New</i>	1	\$ 50.00	\$ 50.00	+
8	BOOTLID NUMBER PLATE GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
9	BOOTLID EMBLEM 'C&C' (SPECAIL TYPE) <i>New</i>	1	\$ 120.00	\$ 120.00	50
10	TAILLAMP CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
11	REAR FENDER DRAIN GARNISH CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	+
12	REAR FENDER COWLING CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
13	REAR FENDER INNER TRIM CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
14	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00	+
15	REAR END PANEL INNER GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	20
16	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200

TOTAL \$ 1,320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	400

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKG3193P**
 MODEL : **MERCEDES C180**
 DATE OF ACCIDENT : 02.08.2024
 TIME OF ACCIDENT : 11:35 HOURS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	60
3	TUFF COAT	\$ 350.00	30
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 380.00	40
6	TRANFER BOOTLID MECHANISM	\$ 80.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
8	REMOVE AND REFIX AND RESET REVERSE SENSOR	\$ 250.00	50
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	x

TOTAL \$ 5,990.00

TOTAL PARTS COST : \$ 13,681.50
 TOTAL LABOUR COST : \$ 5,990.00
 TOTAL REPAIR COST : \$ 19,671.50

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Admin
 F/S 05/08/24.

04 Days