

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURANCE	CE LTD	Ref:	CS/INC24080075/Aqh3m4	
	75 BRAS BASAH RO	OAD SINGAPORE 189557	Date:	24/10/2024	
	INCOME CENTRES	SINGAPORE 109337	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XB 7990B	Veh. Inspected	SMC 7085P	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1289431-001	Excess	\$0.00	
	Assign From	HELENA TAN	Assign Date	06/08/2024	
2.	2. Vehicle Details				
	Make & Model	TOYOTA PRIUS HYBRID	C.C	1797	
	Engine No.	2ZR2A12521	Year of Reg.	18/07/2018	
	Chassis No.	ZVW506129796	Colour	WHITE	
	Odometer	308011 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	185/65R15	BLACKHAWK	6	
	L/H Front Tyre	185/65R15	BLACKHAWK	6	
	R/H Rear Tyre	185/65R15	BLACKHAWK	6	
	L/H Rear Tyre	185/65R15	BLACKHAWK	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND UNDERCARRIAGE.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	04/08/2024	Inspection Date	06/08/2024 (12:36)	
	Survey held at	Survey held at JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days