

COLOUR VIBE PTE. LTD.

176 Sin Ming Dr, #05-16 Sin Ming AutoCare, Singapore 575721

Company Registration No: 202203460Z

Email: business@colourvibe.sg

Contact: (+65) 94594918

Not Withheld
L1 Rm @ 2800h
Merry After Rain
4 days

Car Make/Model: MERCEDES E250 SEDAN (R18)

Date: 30/07/2024

Engine/Chassis No: WDD2120362B146987

Carplate : SKM8999S

LIST ITEM			
DESCRIPTION	QUANTITY	PRICE	TOTAL
REAR BUMPER	1	\$ 1,440.00	\$ <i>Per</i> 1,440.00 ✓
LOWER REAR BUMPER <i>355</i>	1	\$ 390.00	\$ <i>Per</i> 390.00 ✓
COVER TOWING EYE	1	\$ 93.00	\$ <i>CM</i> 93.00 ✓
BRACKET, REAR CENTER OF BUMPER <i>210</i>	1	\$ 346.00	\$ <i>CM</i> 346.00 ✓
BUMPER BASE BRACKET, MIDDLE PART OF REAR BUMPER	1	\$ <i>CM</i> 345.00	\$ <i>Per</i> 345.00 ✓
BRACKET RIGHT SIDE	1	\$ 76.00	\$ <i>Per</i> 76.00 ✓
BRACKET, RIGHT TAIL PIPE	1	\$ 65.00	\$ <i>Per</i> 65.00 ✓
REAR PARKING SENSOR	2	\$ 195.00	\$ <i>Short</i> 390.00 ✓
Luggage compartment switch module Top sensor code A	1	\$ 160.00	\$ <i>Per</i> 160.00 X
Luggage compartment switch module Bottom sensor code B	1	\$ 205.00	\$ <i>Per</i> 205.00 X

SPECIAL NETT ITEM			
DESCRIPTION	QUANTITY	PRICE	TOTAL
BUMPER CLIP (SET)	1	\$ 40.00	\$ <i>Per</i> 40.00 ✓

LABOUR CHARGE			
DESCRIPTION	QUANTITY	PRICE	TOTAL
TO REMOVE & REFIT PDC SENSOR	1	\$ 200.00	\$ 200.00 <i>600</i>
TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	1	\$ 200.00	\$ <i>na</i> 200.00 X
TO PANEL BEAT/ RE-ALIGNMENT	1	\$ 600.00	\$ 600.00 <i>4000</i>
TO SPRAY PAINTING	1	\$ 600.00	\$ 600.00 <i>4500</i>

TOTAL	\$ 5,150.00
-------	-------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: