



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080078/Uvp3
16 RAFFLES QUAY	Date:	19/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3047R	Veh. Inspected	SNC 2768Z
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24006795MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	05/08/2024

### 2. Vehicle Details

Make & Model	VOLKSWAGEN GOLF A7 1.4 TSI AT	C.C	1395
Engine No.	CXS217172	Year of Reg.	15/09/2014
Chassis No.	WVWZZZAUZFW041921	Colour	GREY / RED
Odometer	78425 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40ZR18	MICHELIN	6
L/H Front Tyre	225/40ZR18	MICHELIN	6
R/H Rear Tyre	225/40ZR18	MICHELIN	6
L/H Rear Tyre	225/40ZR18	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	30/07/2024	Inspection Date	07/08/2024
Survey held at	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM) - 3021A UBI ROAD 1, #01-42 SINGAPORE 408715		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days