

LEANG AUTOMOTIVE
BLK 1 KAKI BIKIT AVE 6 #01-68
AUTOBAY S'PORE 417883 HP 90286516

not Authorized
means
7/8/24 1/5 \$2100/
2 days

VEHICLE No: SLN 8958T

1PC	FRONT BUMPER	Dis	\$567.50	✓
1PC	FRONT BUMPER SIDE RETAINER O/S	11	\$28.90	x
1PC	FRONT BUMPER REINFORCEMENT	11	\$213.10	x
1PC	FRONT FENDER O/S	R	\$445.20	x
1PC	FRONT FENDER INNER SHIELD O/S	11	\$168.60	x
1PC	FRONT LOWER ARM O/S	11	\$331.80	x
1PC	FRONT KNUCKLE ARM O/S	11	\$392.50	x
1PC	FRONT KNUCKLE ARM BEARING O/S	11	\$215.00	x
1PC	HEADLAMP O/S	scr/line	\$1,283.10	✓
			\$3,645.70	
			LESS 20%	\$2,916.56

S.NETT

1SET	FRONT BUMPER CLIPS	net	\$40.00	x
1PC	FRONT SPORT RIM O/S	cur/daye	\$800.00	450 s/n
1PC	FRONT TYRE O/S	see	\$200.00	x

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	11	\$50.00 x
TO REFILL AIR CON GAS	11	\$120.00 x
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$750.00	280
TO PUTTY & SPRAY PAINTING	\$750.00	400
TOTAL	\$5,676.56	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P. 18106
202
1480.48
450
700
2630.48
202
2604