

Hui Ruy
7P / NC

ESTIMATE OF REPAIR

Veh# : SKX2113M

Model:

INFINITI Q50

Accident Date : 3/8/2024

30/10/2015

Location : BUKIT BATOK WEST

3P:

SJU9826X (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	2pcs	Headlamp RH & LH <i>could</i>			7,896.40
2	2pcs	Headlamp lower bracket RH & LH <i>could</i>			356.50
3	1 pc	Front support panel <i>could</i>			1,027.20
4	1 pc	Front grille <i>could</i>			824.50
5	1 pc	Front grille chrome moulding <i>new</i>			391.00
6	1 pc	Front grille Logo <i>could</i>			79.00
7	1 set	Front grille clip <i>new</i>		50.00	20
8	1 pc	Front bumper inner air guide RH <i>new</i>			62.00
9	1 pc	Front bumper <i>disturbed</i>			1,104.00
10	1 set	Front bumper clip <i>new</i>		80.00	30
11	1 pc	Front bumper inner sponge <i>could</i>			388.70
12	1 pc	Front bumper upper rubber seal <i>new</i>			49.00
13	1 pc	Front bumper lamp RH <i>new</i>			511.00
14	1 pc	Front bumper reinforcement <i>disturbed</i>			969.00
15	1 pc	Front bumper reinforcement bracket RH <i>new</i>			159.00
16	1 pc	Front bumper lower grille <i>could</i>			136.00
17	1 pc	Front bumper tow hook cover <i>new</i>			47.00
18	2 pcs	Front bumper side retainer R/L <i>new</i>			80.00
19	4 pcs	Front bumper parking sensor <i>2 pins damaged</i>			1372.00
20	1 pc	Front bumper parking sensor wireharness <i>new</i>			403.00
21	2 pcs	Front bumper parking sensor 'O' ring <i>new</i>			24.00
22	4 pcs	Front bumper parking sensor holder bracket <i>could</i>			100.00
23	1 pc	Front bumper fog lamp RH <i>new</i>			462.00
24	1 pc	Front bumper fog lamp cover RH <i>new</i>			170.00
25	1 pc	Front bumper fog lamp cover chrome moulding RH			137.00
26	1 pc	Front bumper day time running light <i>new</i>			655

27	2pcs	Front horn Lh & RH <i>green</i>			630.40	+
28	1 pc	Front intercooler			920.30	+
29	1 pc	Radiator coolant <i>new</i>		80.00		
30	1pc	Rear bumper <i>behind</i>			1040	✓
31	10pcs	Rear bumper clips <i>new</i>		80.00	30	
32	2pcs	Rear bumper screw clips <i>new</i>		20.00	+	
33	2pcs	Rear bumper enforcement o/s & n/s bracket <i>N/s Dented</i>			462.7	231.35
34	2pcs	Rear bumper o/s & n/s reflector <i>green</i>			475.4	+
35	2pcs	Rear bumper o/s & n/s retainer			362.7	+
36	2pcs	Rear reverse sensor <i>2 pieces damaged</i>			1372.00	686
37	2pcs	Rear reverse sensor wire harness <i>new</i>			410.4	+
38	1pc	Rear end panel <i>Repair</i>			850	+
39	1pc	Rear end panel inner trim <i>new</i>			285	+
40	4pcs	Rear end panel inner trim clips <i>new</i>		20	29	+
41	1 pc	Rear enforcement <i>Dented</i>			600.00	✓
42	1 pc	Rear boot cover <i>Dented</i>			1350.00	✓
43	1 pc	Rear boot cover INFINITY EMBLEM <i>green</i>			101.00	✓
44	1 pc	Rear boot cover Q50 EMBLEM			90.00	✓
45	1 pc	Rear boot cover lower chrome <i>new</i>			180.50	✓
Sub-Total:			0.00	310.00	24,743.70	16842.95
			10%	0%	0%	15158.65
After Less %:			0.00	310.00	24,743.70	S.N: 130
Labour						
1		To remove & refix accident damaged parts & realign affected area.		1,500.00		1200
2		To spray painting on accident affected area.		1,500.00		800
3		To remove & refix air-con condenser, hose & refilling gas.		200.00		60
4		To remove & refix radiator, fan motor & other attachment parts.		120.00		60 2210
5		To check wiring & rewire parking sensor.		100.00		50
6		To rust proof affected area.		100.00		40
7		To diagnosis & reset after work.		400.00		+
Sub-Total:				3,920.00		
Total:					28,973.70	

Chan San Choon
Director
DipEng, AAE, MM, MSAE(Aus)



Signature:
Date:

Phone: 17458.65
L/S: 12K ✓
(Nett Value)

Address:
1/8 07/08/24
09 Days