

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YES CAR LEASING PTE LTD
210 TURF CLUB ROAD #LOT-B21 THE
GRANDSTAND
SINGAPORE 287995

Contact : 92970233 89166258

TP Chinn.
Veron.

TAX INVOICE

Repair Code : CLM18329

Date in : 02/08/2024

Vehicle Num. : GBG760D

Model : NISSAN NV350 PANEL VAN 2.5 5AT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0007794/YD25413705A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	600.50	✓ 600.50
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	17.40	+ 34.80
REAR STEP PANEL <i>Dented</i>	1	219.00	✓ 219.00
REAR TAILGATE <i>Dented</i>	1	1842.00	✓ 1,842.00
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	59.70	✓ 59.70
REAR TAILGATE 'NV350' EMBLEM <i>new</i>	1	78.00	✓ 78.00
REAR TAILGATE HINGES L/R <i>new</i>	2	51.60	+ 103.20
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	261.00	+ 261.00
REAR TAILGATE WEATHER STRIP <i>new</i>	1	171.00	✓ 171.00
Subtotal before discount			3,369.20
Percentage discount 10%			336.92
Sub-total 1			3,032.28
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30 80.00
REAR BUMPER REVERSE SENSOR - SET <i>Dented</i>	1	280.00	280.00
REAR END PANEL (OUTER) <i>Rehd</i>	1	296.00	296.00
REAR TAILGATE '70KM' STICKER <i>new</i>	1	25.00	15 25.00
REAR TAILGATE WINDSCREEN SEAL	1	80.00	40 80.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	30 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YES CAR LEASING PTE LTD
210 TURF CLUB ROAD #LOT-B21 THE
GRANDSTAND
SINGAPORE 287995

Contact : 92970233 89166258

TAX INVOICE

Repair Code : CLM18329

Date in : 02/08/2024

Vehicle Num. : GBG760D

Model : NISSAN NV350 PANEL VAN 2.5 5AT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0007794/YD25413705A

	Subtotal before discount	841.00
Percentage discount 0%		0.00
315	Sub-total 2	841.00
	Parts-total	3,873.28

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,330.00
Parts & Labour Total	6,203.28

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts in my business
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 2

Adrian L
2/506/08/24
0427

blm: 4278.18

L/S: 3.41K ✓