

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKB 1913T

	REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR BOOTLID	BENT	\$1,207.75	\$1,112.45	
1	REAR BUMPER LOWER	BENT	\$463.60	\$463.60	
1	REAR END PANEL	BENT	\$892.05	\$731.35	
1	REAR LAMP	CRACKED	\$955.60	\$768.10	
1	REAR BOOTLID GARNISH	MTG CRACKED	\$1,155.60	\$925.60	
1	REAR BUMPER	BUCKLED	\$468.20	\$468.20	
1	REAR END PANEL GARNISH	MTG DISTORTED	\$316.20	\$316.20	
1	REAR BOOTLID LAMP	CRACKED	\$631.90	\$631.90	
1	REAR BUMPER TOWING COVER	DENTED	\$26.80	\$26.80	
2	REVERSE SENSOR @220	SHORTED (1PC ONLY)	\$440.00	\$220.00	
1	REAR BUMPER REINFORCEMENT	BENT	\$369.00	\$369.00	
	LESS 25.00% DISCOUNT		(\$1,731.68)	(\$1,508.30)	
			\$5,195.02	\$4,524.90	

Labour				
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted	
TO REMOVE REAR WINDSCREEN		\$180.00	\$120.	
TO RESPRAY AFFECTED PARTS		\$800.00	\$720.	
TO REPLACE ABOVE PARTS		\$800.00	\$600.	
TO CHECK WIRING		\$30.00	\$20.	
ANTI RUST		\$50.00	\$50.	
	1	\$1,860.00	\$1,510	
GRAND TOTAL		\$7,055.02	\$6,034.	
			<u>.</u> I	

KSC

KENNETH KONG SENG CHEONG



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.