



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LONPAC INSURANCE BHD		Ref:		CS/LPC24080083/Knh3m4
300 BEACH ROAD		Date:		29/08/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555		Code:		LPC2
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 9962A	Veh. Inspected	SKB 1913T	
Policy No.	-	Coverage	0	
Claim No.	23/24/24/VC05/029635	Excess	\$0.00	
Assign From	CHARMAINE KONG	Assign Date	06/08/2024	
2. Vehicle Details				
Make & Model	TOYOTA C-HR (A)	C.C	1797	
Engine No.	2ZR8245048	Year of Reg.	18/12/2017	
Chassis No.	ZYX102086525	Colour	METALLIC RED	
Odometer	115438 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	225/50R18	MICHELIN	9	
L/H Front Tyre	225/50R18	MICHELIN	9	
R/H Rear Tyre	225/50R18	MICHELIN	9	
L/H Rear Tyre	225/50R18	MICHELIN	9	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/08/2024	Inspection Date	06/08/2024	
Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				