

ESTIMATE RC AUTO

Not Authored
Respray B4 paint
5 days
B6034-90

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

SKB 1913 T

Date : 15.08.2024

Quantity	Description/Particular	Unit Price	Amount	
1 PC	REAR BOOTLID 1112.45		B1 1207	75 ✓
1 PC	REAR BUMPER SPOILER 1000		B1 463	60 ✓
1 PC	REAR END PANEL 731.35		B1 892	05 ✓
1 PC	REAR LAMP 768.10		CNT 955	60 ✓
1 PC	REAR BOOTLID GANISH 925.60		mg CNT 1155	60 ✓
1 PC	REAR BUMPER		Bu 468	20 ✓
1 PC	REAR END PANEL GANISH		mg B1 316	20 ✓
1 PC	REAR BOOTLID LAMP		CNT 631	90 ✓
1 PC	REAR BUMPER TOWING COVER		Del 26	80 ✓
1-2 PCS	REVERSE SENSOR@220		short 440	00 ✓
	Per bumper reinforcement B1 369.00 ✓	TOTAL	6557	70
		LESS 25	4918	27
	TO REMOVE REAR WINDSCREEN		180	00 1200 ✓
	TO RESPRAY AFFECTED PARTS		800	00 7200 ✓
	TO REPLACE ABOVE PARTS		800	00 6000 ✓
	TO CHECK WIRING		30	00 200 ✓
	ANTI RUST		50	00 ✓
		TOTAL	6778	75

Received the above goods in good order and condition

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: E & O.E.

Date:

for

RC AUTO

Received by

Authorised Signature