



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080085/Rnp3e2
16 RAFFLES QUAY	Date:	28/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 6223J	Veh. Inspected	SNP 6931Z
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006819MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	05/08/2024

2. Vehicle Details

Make & Model	TOYOTA NOAH HYBRID 1.8X	C.C	1797
Engine No.	2ZR2Z08361	Year of Reg.	04/03/2024
Chassis No.	ZWR900160835	Colour	BLACK
Odometer	35768 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60 R16	PROXES	6
L/H Front Tyre	205/60 R16	PROXES	6
R/H Rear Tyre	205/60 R16	PROXES	6
L/H Rear Tyre	205/60 R16	PROXES	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/07/2024	Inspection Date	19/08/2024
Survey held at	LAY AUTO GARAGE PTE LTD - 48 TOH GUAN ROAD EAST #02- 104/103 SINGAPORE 608586		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days