



LAY AUTO GARAGE PTE LTD

48 TOH GUAN ROAD EAST #02-103/104 SINGAPORE 608586

Company & GST Registration No : 201928455Z

FIONA : 87973443 Email:Fiona@layuauto.com

LAY AUTO LEASING PTE LTD

No.48 # 02-104

TOH GUAN ENTERPRISE HUB

SINGAPORE 608586

15th Aug 2024

ESTIMATE COST OF REPAIR SNP6931Z

1PC REAR BUMPER *de*

Less 25%

\$2,500.00	1417.45
-\$625.00	252
<u>\$1,875.00</u>	<u>1063.08</u>

SPECIAL NETT ITEMS

1PCS FRONT SENSOR *3 XM*

~~\$332.64~~ X

Labour Charge, remove, renew , repair and align replacement part's.

~~\$800.00~~ 500

Remove and refix rear bumper *

~~\$120.00~~ *Xm* 1060

Wiring and test electrical -circuit

~~\$80.00~~ 60

Spray Painting

~~\$500.00~~ /

Total Lump Sum Repair

\$3,707.64

1063.08
1060.00
2123.08
202
1698.46
45 - \$1,700 / 3 days

Rasul
Hp 90010068

3 days

45

19/08/24

Rey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: