



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMW 5229A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR DOOR RH	TO REPAIR SEE LABOUR	\$1,050.10	\$0.00
1	REAR DOOR WEATHERSTRIP RH	SERVICEABLE	\$250.60	\$0.00
1	REAR DOOR PROTECTIVE STICKER RH	NECESSARY	\$83.20	\$83.20
1	REAR FENDER RH	TO REPAIR SEE LABOUR	\$1,209.50	\$0.00
1	REAR FENDER INNER SHIELD RH	SERVICEABLE	\$358.20	\$0.00
1	SIDE SKIRT RH	TO REPAIR SEE LABOUR	\$680.80	\$0.00
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	LESS 20.00% DISCOUNT		(\$726.48)	(\$16.64)
			\$2,905.92	\$66.56

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR DOOR INNER TRIM BOARD CLIPS RH (SN)	NOT NECESSARY	\$50.00	\$0.00
1	REAR FENDER QUARTER GLASS SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR FENDER INNER SHIELD CLIPS RH (SN)	NOT NECESSARY	\$40.00	\$0.00
			\$170.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF REAR DOOR RH, REAR FENDER RH, SIDE SKIRT RH AND REAR BUMPER		\$1,000.00	\$400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH, SIDE SKIRT, RH REAR BUMPER & ETC		\$1,000.00	\$600.00
	LABOUR CHARGES TO REMOVE & REINSTALL REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH	NOT NECESSARY	\$120.00	\$0.00
	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER QUARTER GLASS & ETC	NOT NECESSARY	\$150.00	\$0.00
	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH	NOT NECESSARY	\$350.00	\$0.00
	TO CHECK WIRING & ELECTRICAL SYSTEM		\$120.00	\$15.00
			\$2,740.00	\$1,015.00

GRAND TOTAL			\$5,815.92	\$1,081.56
--------------------	--	--	-------------------	-------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)		\$1,081.56
Report Ref No: CS/AGI24080087/Kvp3e2			

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.