



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

*zoomautowerks@gmail.com

LKK Auto Consultants henceforth
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Not Authorized
in
moss
6/8/24
1/s \$ 11,600
telephone. After 14 days.

REG NO.: SJX 228 R
MAKE/MODEL: MERCEDES BENZ C200

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
-----	-------------	---------

LIST ITEMS

1	Front headlamp -RH	\$ 17	3,617.00 X
1	Front bumper	1632.81 \$ car/trim	1,887.00 ✓
1	Front wheel rim -RH	\$ car	1,550.00 ✓ 800 S/W
1	Front fender -RH	1215.22 \$ car/trim	1,885.00 ✓
1	Front fender inner shield	\$ 17	285.00 X
1	Front door -RH	\$ 305.00	3,100.00 ✓
1	Front door checker	\$ 50	155.00 X
2	Front door hinges	\$ 17	330.00 ✓
1	Front door inner board	\$ 17	1,000.00 ✓
1	Front door lock	\$ 17	435.00 X
1	Front door regulator	425.21 \$ car/trim	650.00 ✓
1	Front door regulator motor	\$ 80	590.00 X
1	Front door weatherstrip	\$ 100	286.00 ✓
1	Rocker panel side skirt	\$ car/trim	987.00 ✓
1	Rear bumper	1655.32 \$ car/trim	2,085.00 ✓
1	Rear wheel rim -RH	\$ car	1,550.00 ✓ 800 S/W
1	Rear fender -RH	\$ car	1,985.00 ✓
1	Rear fender inner shield	\$ 17	115.00 X
		102	\$ 22,492.00
		Less 5%	\$ 1,124.60
			\$ 21,367.40

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	\$ 100	80.00 50
1	Front fender inner shield clip (1 set)	\$ 17	80.00 X
1	Rear bumper clip (1 set)	\$ 100	80.00 50
1	Rear fender inner shield clip (1 set)	\$ 17	80.00 X
1	Wrapping sticker (1 set) (KIV)	\$ 100	3,500.00 X
			\$ 3,820.00

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00	20
2	To remove, replaced damaged lamps and check up rear wiring.	\$ 17	80.00 X
3	To remove and refit inner garnishes.	\$ 200.00	80
4	To conduct wheel alignment.	\$ 150.00	80
	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$ 200.00	80
5	To apply undercoating.	\$ 150.00	60
6	Panel beating.	\$ 2,800.00	1000
7	To re-spray painting on the affected areas.	\$ 2,500.00	1400
8		\$ 6,160.00	

GRAND TOTAL :

\$ 31,347.40

P-1128850
102
10457.90
1700
2720