

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMK 8345R

	REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	FRONT BUMPER	CUT / TORN	\$878.30	\$878.30	
1	FRONT BUMPER SIDE RETAINER O/S	CRACKED	\$78.20	\$78.20	
1	FRONT BUMPER FOG LAMP GARNISH O/S	GRAZED / TORN	\$111.80	\$111.80	
1	FRONT BUMPER FOG LAMP O/S	CRACKED	\$425.10	\$425.10	
1	SET FRONT BUMPER CLIPS	NECESSARY	\$45.00	\$45.00	
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$520.20	\$0.00	
1	HEADLAMP ASSY O/S	CRACKED	\$3,665.10	\$3,665.10	
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	\$988.20	\$0.00	
1	FRONT FENDER INNER SHIELD O/S	TORN	\$201.20	\$201.20	
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	\$39.00	\$39.00	
1	FRONT SPORT RIM O/S	TO REPAIR SEE LABOUR	\$850.00	\$0.00	
1	FRONT KNUCKLE ARM O/S	NOT NECESSARY	\$552.10	\$0.00	
1	FRONT KNUCKLE ARM BEARING O/S	NOT NECESSARY	\$250.00	\$0.00	
	LESS 25.00% DISCOUNT		(\$2.151.05)	(\$1.360.93)	

Labour					
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
TO CHECK WIRING		\$50.00	\$20.00		
TO CONDUCT WHEEL ALIGNMENT		\$120.00	\$60.00		
TO DISMANTLE FRONT UNDERCARRIAGE	NOT NECESSARY	\$180.00	\$0.00		
TO SPRAY RUST PROOFING	NOT NECESSARY	\$50.00	\$0.00		
LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S AND FRONT SPORT RIM O/S		\$680.00	\$320.00		
TO PUTTY & SPRAY PAINTING		\$900.00	\$400.00		
		\$1,980.00	\$800.00		
GRAND TOTAL		\$8,433.15	\$4,882.77		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,900.00		
Report Ref No: CS/TP14924060092/Uqp3					

\$6,453.15

\$4,082.77



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## **CKS**

MARCUS CHUA KANG SENG Licensed Appraiser