



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP14924060092/Uqp3e2	
BLK 1 KAKI BUKIT AVE 6		Date:	22/07/2024	
#01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		Code:	TP149	
ON BEHALF OF AL AUTORENT PTE. LTD.				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	-	Veh. Inspected	SMK 8345R	
Policy No.	-	Coverage	0	
Claim No.	-	Excess	\$0.00	
Assign From	-	Assign Date	13/06/2024	
2. Vehicle Details				
Make & Model	TOYOTA COROLLA ALTIS (A)		C.C	1598
Engine No.	1ZRY115990		Year of Reg.	20/11/2014
Chassis No.	MR053REH104519449		Colour	SILVER
Odometer	409281 KM		Steering	IN ORDER
Brakes	IN ORDER		General	GOOD
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
		Size	Make	Balance (mm)
R/H Front Tyre		205/55R16	TRANSFORCE	6
L/H Front Tyre		205/55R16	TRANSFORCE	6
R/H Rear Tyre		205/55R16	TRANSFORCE	6
L/H Rear Tyre		205/55R16	TRANSFORCE	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/05/2024		Inspection Date	13/06/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

