



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP14924060092/Uqp3e2
BLK 1 KAKI BUKIT AVE 6		Date:	22/07/2024
#01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		Code:	TP149
ON BEHALF OF AL AUTORENT PTE. LTD.			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	-	Veh. Inspected	SMK 8345R
Policy No.	-	Coverage	0
Claim No.	-	Excess	\$0.00
Assign From	-	Assign Date	13/06/2024
<b>2. Vehicle Details</b>			
Make & Model	TOYOTA COROLLA ALTIS (A)	C.C	1598
Engine No.	1ZRY115990	Year of Reg.	20/11/2014
Chassis No.	MR053REH104519449	Colour	SILVER
Odometer	409281 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	TRANSFORCE	6
L/H Front Tyre	205/55R16	TRANSFORCE	6
R/H Rear Tyre	205/55R16	TRANSFORCE	6
L/H Rear Tyre	205/55R16	TRANSFORCE	6
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	13/05/2024	Inspection Date	13/06/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.			
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			