

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

not Authorized
for
merch
13/6/24 d/s 3900/
the ph...
d/s

VEHICLE No: SMK 8345R

1PC	FRONT BUMPER	cut/torn	\$878.30	✓
1PC	FRONT BUMPER SIDE RETAINER O/S	one	\$78.20	✓
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	gross/torn	\$111.80	✓
1PC	FRONT BUMPER FOG LAMP O/S	one	\$425.10	✓
1SET	FRONT BUMPER CLIPS	new	\$45.00	✓
1PC	FRONT BUMPER REINFORCEMENT	11	\$520.20	X
1PC	HEADLAMP ASSY O/S	one	\$3,665.10	✓
1PC	FRONT FENDER O/S	R	\$988.20	X
1PC	FRONT FENDER INNER SHIELD O/S	torn	\$201.20	✓
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	new	\$39.00	✓
1PC	FRONT SPORT RIM O/S	new	\$850.00	X
1PC	FRONT KNUCKLE ARM O/S	11	\$552.10	X
1PC	FRONT KNUCKLE ARM BEARING O/S	11	\$250.00	X
			\$8,604.20	
			LESS 25%	\$6,453.15

TO CHECK WIRING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE FRONT UNDER CARRIAGE
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
	\$120.00	60
11	\$180.00	X
11	\$50.00	X
	\$680.00	320
	\$900.00	400
TOTAL	\$8,433.15	

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts in a prominent way
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-54437
25%
4082.78
800
4882.78
212
7906