

BLUWEL AUTOMOTIVE SERVICE PTE LTD  
1 KAKI BUKIT AVE 6 # 01-28/53/55/56  
SINGAPORE 417883 TEL :67452088

VEHICLE No: SMK 8345R

1PC	FRONT BUMPER	\$878.30
1PC	FRONT BUMPER SIDE RETAINER O/S	\$78.20
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	\$111.80
1PC	FRONT BUMPER FOG LAMP O/S	\$425.10
1SET	FRONT BUMPER CLIPS	\$45.00
1PC	FRONT BUMPER REINFORCEMENT	\$520.20
1PC	HEADLAMP ASSY O/S	\$3,665.10
1PC	FRONT FENDER O/S	\$988.20
1PC	FRONT FENDER INNER SHIELD O/S	\$201.20
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	\$39.00
1PC	FRONT SPORT RIM O/S	\$850.00
1PC	FRONT KNUCKLE ARM O/S	\$552.10
1PC	FRONT KNUCKLE ARM BEARING O/S	\$250.00
		\$8,604.20
	LESS 25%	\$6,453.15

TO CHECK WIRING	\$50.00
TO CONDUCT WHEEL ALIGNMENT	\$120.00
TO DISMANTLE FRONT UNDER CARRIAGE	\$180.00
TO SPRAY RUST PROOFING	\$50.00
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$680.00
TO PUTTY & SPRAY PAINTING	\$900.00
TOTAL	\$8,433.15

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: