

ASS. REC. BY:

REF:

MSG / CS/MSG24080091/Kvp3e2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SKE 9166P

Policy No. 1000659019

Claims No. 369194

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 3

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

S + RS. SI

: Fines

: Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

1)

Date/Time, File Return to?

2)

12/8 / 1 Pmg @ 3700h Culu (red 4332.54, 53%)

COLOUR VIBE PTE. LTD.

176 Sin Ming Dr, #05-16 Sin Ming AutoCare, Singapore 575721

Company Registration No: 202203460Z

Email: business@colourvibe.sg

Contact: (+65) 94594918

Car Make/Model: BMW X3

Date: 05/08/2024

Engine/Chassis No: WBATS720109G42624

Carplate : SGJ58Z

LIST ITEM				
DESCRIPTION		QUANTITY	PRICE	TOTAL
REAR BUMPER	1562.95	1	\$ 2,165.40	\$ 2,165.40
REAR BUMPER LOWER TRIM		1	\$ 473.15	\$ 473.15
REAR, RIGHT BUMPER MOUNTING BRACKET		1	\$ 275.25	\$ 275.25
REINFORCE BUMPER REAR LOWER PART		1	\$ 224.55	\$ 224.55
REAR RADAR SENSOR RH	1280	1	\$ 1,565.45	\$ 1,565.45
REAR TAIL LAMP, BODY		1	\$ 680.40	\$ 680.40
REAR FENDER TRIM	205.50	1	\$ 345.00	\$ 345.00
REAR SENSOR	325.40	1	\$ 473.34	\$ 473.34
			58	\$ 6,202.54

SPECIAL NETT ITEM			
DESCRIPTION	QUANTITY	PRICE	TOTAL
FENDER RIVET	6	\$ 5.00	\$ 30.00
LABOUR CHARGE			
DESCRIPTION	QUANTITY	PRICE	TOTAL
TO REMOVE, REPLACED DAMAGE LAMPS & CHECK WIRING	1	\$ 200.00	\$ 200.00
TO REMOVE & REFIT PDC SENSOR	1	\$ 200.00	\$ 200.00
TO PANEL BEAT/ RE-ALIGNMENT	1	\$ 800.00	\$ 800.00
TO SPRAY PAINTING	1	\$ 400.00	\$ 400.00
TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	1	\$ 200.00	\$ 200.00

Not Withstand
L1 Rep @ 3700h
Rehman After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: