

COLOUR VIBE PTE. LTD.

176 Sin Ming Dr, #05-16 Sin Ming AutoCare, Singapore 575721

Company Registration No: 202203460Z

Email: business@colourvibe.sg

Contact: (+65) 94594918

Car Make/Model: BMW X3

Date: 05/08/2024

Engine/Chassis No: WBATS720109G42624

Carplate : SGJ58Z

LIST ITEM				
DESCRIPTION	QUANTITY	PRICE	TOTAL	
REAR BUMPER <i>1562.95</i>	1	\$ 2,165.40	\$	2,165.40
REAR BUMPER LOWER TRIM	1	\$ 473.15	\$	473.15
REAR, RIGHT BUMPER MOUNTING BRACKET	1	\$ 275.25	\$	275.25
REINFORCE BUMPER REAR LOWER PART	1	\$ 224.55	\$	224.55
REAR RADAR SENSOR RH <i>1280</i>	1	\$ 1,565.45	\$	1,565.45
REAR TAIL LAMP, BODY	1	\$ 680.40	\$	680.40
REAR FENDER TRIM <i>205.50</i>	1	\$ 345.00	\$	345.00
REAR SENSOR <i>325.40</i>	1	\$ 473.34	\$	473.34
			\$	6,202.54

SPECIAL NETT ITEM			
DESCRIPTION	QUANTITY	PRICE	TOTAL
FENDER RIVET	6	\$ 5.00	\$ 30.00
LABOUR CHARGE			
DESCRIPTION	QUANTITY	PRICE	TOTAL
TO REMOVE, REPLACED DAMAGE LAMPS & CHECK WIRING	1	\$ 200.00	\$ 200.00
TO REMOVE & REFIT PDC SENSOR	1	\$ 200.00	\$ 200.00
TO PANEL BEAT/ RE-ALIGNMENT	1	\$ 800.00	\$ 800.00
TO SPRAY PAINTING	1	\$ 400.00	\$ 400.00
TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	1	\$ 200.00	\$ 200.00

Not Withstand
 21 Rp @ 370dp
 Recovery After Paint
 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: