



EMPIRE AUTO PTE LTD

60 PAYA LEBAR ROAD, #07-54 PAYA LEBAR SQUARE S(409051)

Sompo Japan Insurance Company (Asia) Pte Ltd

50 Raffles Place

#03-03 Land Tower

Singapore 048623

ATTN: MOTOR CLAIM DEPARTMENT

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SNN8042L

MODEL : AUDI A3

POLICY NO :

CHASSIS WAUZZZ8V6KA044371

YEAR OF MANUFACTURE : 2018

DATE / TIME OF ACCIDENT: 03/08/2024 Time: 1540HRs at CTE(SLE AFTER ORCHARD ENTRANCE

THIRD PARTY VEHICLE NO: GMP6206X

Date: 02/08/2024

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Amount
S/N			S\$	S\$
1	FRONT BUMPER <i>tan</i>	1	\$ 2,711.21	\$ 2,711.21 ✓
2	FRONT BUMPER RETAINER LH <i>green</i>	1	\$ 88.20	\$ 88.20 +
3	FRONT BUMPER RETAINER RH <i>green</i>	1	\$ 88.20	\$ 88.20 +
4	FRONT BUMPER TOW COVER <i>new</i>	1	\$ 205.00	\$ 205.00 +
5	FRONT GRILLE <i>black</i>	1	\$ 1,884.14	\$ 1,884.14 ✓
6	FRONT HEADLAMP RH <i>black</i>	1	\$ 9,647.00	\$ 9,647.00 +
7	FRONT HEADLAMP LH <i>black</i>	1	\$ 9,647.00	\$ 9,647.00 ✓
8	FRONT HEADLAMP RETAINER <i>new</i>	11	\$ 192.63	\$ 192.63 +
9	FRONT FENDER RH <i>green</i>	1	\$ 1,316.14	\$ 1,316.14 +
10	FRONT FENDER LH <i>green</i>	1	\$ 1,316.14	\$ 1,316.14 +
11	FRONT FENDER INNER CROWLING <i>green</i>	1	\$ 305.50	\$ 305.50 +
12	FRONT FENDER INNER CROWLING LH <i>green</i>	1	\$ 305.50	\$ 305.50 +
13	FRONT GRILLE <i>black</i>	1	\$ 1,984.55	\$ 1,984.55 ✓
14	FRONT LOWER GRILLE <i>new</i>	1	\$ 1,142.12	\$ 1,142.12 +
15	FRONT REINFORMENT BAR <i>new</i>	1	\$ 833.41	\$ 833.41 +
16	FRONT BUMPER SPONAGE <i>black</i>	1	\$ 262.10	\$ 262.10 +
17	FRONT SUPPORT PANEL <i>green</i>	1	\$ 2,200.12	\$ 2,200.12 +
18	FRONT SUPPORT TOP GANISH <i>green</i>	1	\$ 899.36	\$ 899.36 +
19	RADIATOR <i>green</i>	1	\$ 1,828.11	\$ 1,828.11 +
20	CONDENSER <i>green</i>	1	\$ 1,389.90	\$ 1,389.90 +
21	FAN BLADE <i>green</i>	1	\$ 299.60	\$ 299.60 +
22	FAN MOTOR <i>green</i>	1	\$ 887.14	\$ 887.14 +
23	BONNET <i>black</i>	1	\$ 3,218.90	\$ 3,218.90 ✓
24	BONNET LOCK <i>new</i>	1	\$ 838.00	\$ 838.00 +
25	TAILGATE <i>new</i>	1	\$ 3,844.00	\$ 3,844.00 +
26	TAILGATE DAMPER RH <i>new</i>	1	\$ 200.00	\$ 200.00 +
27	TAILGATE DAMPER LH <i>new</i>	1	\$ 200.00	\$ 200.00 +
28	TAILGATE LAMP RH <i>new</i>	1	\$ 889.14	\$ 889.14 +
29	TAILGATE LAMP LH <i>new</i>	1	\$ 889.14	\$ 889.14 +

30	REAR WINDSCREEN WITH MOULDING	3rd	1	\$ 1,118.30	\$ 1,118.30	+
31	TAILGATE WEATHER STRIP	3rd	1	\$ 350.00	\$ 350.00	+
32	AUDI EMBLEM		1	\$ 206.00	\$ 206.00	+
33	A3 WORDING		1	\$ 152.44	\$ 152.44	+
34	REAR LAMP RH	He new	1	\$ 789.14	\$ 789.14	+
35	REAR LAMP LH		1	\$ 789.14	\$ 789.14	+
36	TAILGATE BOARD GANISH	He new	1	\$ 597.63	\$ 597.63	+
37	TAILGATE LOCK		1	\$ 357.12	\$ 357.12	+
38	TAILGATE STRICKER		1	\$ 99.00	\$ 99.00	+
39	REAR END PANEL	not in	1	\$ 1,396.82	\$ 1,396.82	+
40	REAR END PANEL TOP GANISH	new	1	\$ 352.91	\$ 352.91	+
41	REAR REINFORMENT BAR	new	1	\$ 747.70	\$ 747.70	+
42	SPARE TIRE PANEL	He new	1	\$ 1,518.62	\$ 1,518.62	+
43	SPARE TIRE BOARD		1	\$ 595.63	\$ 595.63	+
44	SPARE TIRE TOOL SPONGE		1	\$ 460.82	\$ 460.82	+
45	REAR FENDER INNER TRIM RH		1	\$ 969.81	\$ 969.81	+
46	REAR FENDER INNER TRIM LH	He new	1	\$ 969.81	\$ 969.81	+
47	REAR FENDER RH		1	\$ 3,668.44	\$ 3,668.44	+
48	REAR FENDER LH		1	\$ 3,668.44	\$ 3,668.44	+
49	REAR BUMPER	Deland	1	\$ 2,483.00	\$ 2,483.00	✓
50	REAR BUMPER RETAINER RH	He new	1	\$ 83.70	\$ 83.70	+
51	REAR BUMPER RETAINER LH		1	\$ 83.70	\$ 83.70	+
52	REAR BUMPER RELECTOR RH	new	1	\$ 70.00	\$ 70.00	+
53	REAR BUMPER REFLECTOR LH	cancel	1	\$ 70.00	\$ 70.00	✓
54	REAR BUMPER DIFFUSAL	Deland	1	\$ 496.50	\$ 496.50	✓
55	REVERSE SENSOR	2 pieces damaged	4	\$ 421.00	\$ 1,684.00	520
56	REVERSE SENSOR SEAL	new 2 pieces	4	\$ 24.00	\$ 96.00	48
57	EXHUAUST ASSY	Best	1	\$ 6,556.50	\$ 6,556.50	+
58	SUNDRIES	new	1	\$ 300.00	\$ 300.00	+

Sub-Total: 80,243.42
Less: 5% discount - 4,012.17
Total Parts after 5% discount: 76,231.25

Special Nett Items

1	ANTI-RUST COATING	new	4	80.00	320.00	+
2	FRONT BUMPER CLIPS	new	1	125.00	125.00	30
3	FRONT NUMBER PLATE	Best	1	100.00	100.00	50
4	FRONT FENDER CLIPS	new	1	100.00	100.00	+
5	FRONT FENDER CROWLING CLIPS	new	1	100.00	100.00	+
6	REAR PANEL SEALANT	new	1	\$ 150.00	\$ 150.00	+
7	REAR NUMBER PLATE WITH CASING	not in	1	\$ 100.00	\$ 100.00	+
8	REVERSE CAMERA SET	new	1	\$ 500.00	\$ 500.00	+
9	SPARE TIRE PANEL SEALANT	new	1	\$ 120.00	\$ 120.00	+
10	REAR BUMPER CLIPS	new	1	\$ 80.00	\$ 80.00	30
11	INSULATOR CLIPS	He new	1	\$ 80.00	\$ 80.00	+
12	REAR WINDSCREEN SEALANT	He new	1	\$ 120.00	\$ 120.00	+

Total Parts: 1,895.00

Labour Charges For FRONT

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	1,500.00	400
2	Provide skill labour & material to putty all damaged parts & panel & to	1,500.00	400
3	Provide skill labour to disconnect and check electrical wiring	150.00	30
4	Reset Engine Management system with diagnostic fault	500.00	+
5	RnR aircon condenser, pipe and radiator to facillite repair	180.00	+
6	Headlamp reprograming	500.00	+

Labour Charges For REAR

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	1,800.00	200
2	Provide skill labour & material to putty all damaged parts & panel & to	1,800.00	400
3	Provide skill labour to disconnect and check electrical wiring		
4	Dimantle and transfer door fitting and mechanisim to new TAILGATE	180.00	60
5	Labour to remove and install rear camera		
6	Provide skill labour to remove and reinstall rear interior compartment trims to facillite repair	150.00	+
7	Provide skill labour to remove and reinstall exhaust to facillite repair	200.00	100
8	RnR rear windscreen to facillite repair	200.00	+

Total Labour:

**Total Parts & Labour:
Grand Total:**

8,660.00
86,786.25
86,786.25

Estimate Repair Duration

8 days

ACCIDENT VEHICLE OF : SNN8042L

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Adrian C
1/8 06/08/24.

07 Days

Survey attended by:

Name : _____

Company : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____