



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24080093/Eqp3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	03/09/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 1209G	Veh. Inspected	SHD 1076J
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/034(CF)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	06/08/2024

2. Vehicle Details

Make & Model	KIA NIRO PLUS HYBRID	C.C	1580
Engine No.	G4LEPS252939	Year of Reg.	16/04/2024
Chassis No.	KNAA381CVRT021076	Colour	SILVER
Odometer	27207 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55 R17	NEXEN	6
L/H Front Tyre	215/55 R17	NEXEN	6
R/H Rear Tyre	215/55 R17	NEXEN	6
L/H Rear Tyre	215/55 R17	NEXEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/07/2024	Inspection Date	06/08/2024
Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL - 23 CHANGI SOUTH AVE 2 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days