

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodland
FAX Number
Estimator Te
Accident Rep

Date Generated

User ID

Section A - Accident Details

Registration Number	SHD1076J
Case Reference Number	TAX/07/24/2039
Registration Date	12/4/2024
Company Type	Strides Premier Taxi Pte Ltd
Make	KIA
Model	NIROPLUS
Name of Driver	LAKHVINDAR SINGH S/O TARA SINGH
Type of Accident	Head to Rear
Accident Date and Time	11/7/2024 5:45 PM
Accident Reported Date and Time	12/7/2024 11:58 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121823
Special Instruction to ARC, if any	DAMAGE TO THE LEFT REAR OF TAXI VEHICLE STILL IN TP COMPOUND 12/7/2024
Prepared Date and Time	2/8/2024 2:57 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,690.00	\$0.00
Total Spray Cost	\$1,856.00	\$0.00
Total Spare Part Cost	\$6,497.56	\$0.00
Total Other Cost	\$776.00	\$0.00
TOTAL COST	\$10,819.56	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	02/08/2024 3:27 PM	
Signature		x
Remarks		

Slip (LKK)
6/8/24, 4.00pm
W L

PIP
My AC sy
6 days

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR LH REAR PORTION	\$1,690.00	800
Total Labour	\$1,690.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY REAR FENDER LH	\$378.00	200
TO RESPRAY REAR CHASSIS LH	\$220.00	X
TO RESPRAY REAR LH WHEEL HOUSE	\$220.00	100
TO RESPRAY FUEL LID COVER	\$220.00	X
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY REAR PANEL	\$220.00	100
TO RESPRAY REAR SKID PLATE	\$220.00	100
Total Spray Painting & Panel Beating	\$1,856.00	1500

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TOWING CHARGE	\$56.00	Bill / n/c
TO WASH AND VACUUM	\$60.00	X n/c
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	30 n/c
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	20 n/c
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	X n/c
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	80 n/c
TO REPLACE SUNDRY PARTS	\$100.00	X n/c
Total Other Costs	\$776.00	186

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		87850DB000	GARNISH ASSY-C.PILLAR,LH	1.00	\$105.80	10.00	\$95.22	Replace X ENT	nn
		87810DB020	GLASS & MOULDING ASSY-QUARTER FIXED,LH	1.00	\$108.10	10.00	\$97.29	Replace X ?	x nn
		87830DB000	GARNISH ASSY-QTR FIXED,LH	1.00	\$424.35	10.00	\$381.92	Replace X	nn
		861792V000	CLIP	10.00	\$5.75	10.00	\$51.75	Replace X	nn
		87741G5000	GARNISH ASSY-QTR SIDE,LH	1.00	\$165.60	10.00	\$149.04	Replace X	nn
		87716G5000	CLIP-SIDE GARNISH MTG	1.00	\$1.15	10.00	\$1.03	Replace X	nn
		86610DB000	COVER-RR BUMPER,UPR	1.00	\$615.25	10.00	\$553.73	Replace / BR	
		86612DB020	COVER-RR BUMPER LWR	1.00	\$637.10	10.00	\$573.39	Replace / BR	
		86613G5000	BRACKET ASSY-RR BUMPER SIDE,LH	1.00	\$28.75	10.00	\$25.88	Replace / BR	
		86663DB000	COVER-RR BUMPER FOG LAMP,LH	1.00	\$26.45	10.00	\$23.81 23.80	Replace / BR	
		86631DB000	BEAM-RR BUMPER	1.00	\$691.15	10.00	\$622.04	Replace / BR	622.03/
		86641DB000	STAY-RR BUMPER LH	1.00	\$67.85	100.00	\$0.00	Repair ? x	nn
		86671DB000	SKID PLATE-RR BUMPER	1.00	\$120.75	10.00	\$108.68	Replace / BR	108.67 /
		86681G5500	MOULDING ASSY-RR BUMPER SIDE,LH	1.00	\$17.25	10.00	\$15.53	Replace / MIS	
		86695G5500	COVER-RR BUMPER SIDE UNDER,LH	1.00	\$13.80	10.00	\$12.42	Replace / CRN	

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		91880DB050	WIRING HARNESS-RR BUMPER	1.00	\$349.60	10.00	\$314.64	Replace X nn	
		92405DB000	LAMP ASSY-BACK UP, LH	1.00	\$204.70	10.00	\$184.23 /	Replace / CMT	
		99310S1900KC	ULTRASONIC SENSOR-S.P.A.S	4.00	\$203.55	10.00	\$732.78	Replace X nn	
		69100DB000	PANEL ASSY-BACK	1.00	\$604.90	10.00	\$544.41	Replace X R	
			CLIPS PIECE, RR BUMPER	10.00	\$4.80	10.00	\$43.20 /	Replace / MC	
		71503DBC10	PANEL ASSY-QUARTER OUTER, LH	1.00	\$1,388.05	10.00	\$1,249.25	Replace - MC	1249.24 /
		71550DB000	EXTENSION ASSY-QTR OTR RR LH	1.00	\$131.10	10.00	\$117.99	Replace X R	
		86821DB000	GUARD ASSY-REAR WHEEL, LH	1.00	\$293.25	10.00	\$263.93 /	Replace - TN	
			STICKER LOGO (RR FENDER)	1.00	\$50.00	0.00	\$50.00 /	Replace - MC	
		87130DB000	GARNISH ASSY-"D" PILLAR, LH	1.00	\$234.60	10.00	\$211.14	Replace X nn	
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00 /	Replace - MC	
		97510AA000	GRILLE ASSY-AIR EXTRACTOR	1.00	\$41.40	10.00	\$37.26 /	Replace - RR	
Total					\$6,572.05		\$6,497.56		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Cl
Total									

3800.31

= 5486.31