



Section A - Accident Details	
Registration Number	SHD1076J
Case Reference Number	TAX/07/24/2039
Registration Date	12/Apr/2024
Company Type	Strides Premier Taxi Pte Ltd
Make	KIA
Model	NIROPLUS
Name of Driver	LAKHVINDAR SINGH S/O TARA SINGH
Type of Accident	Head to Rear
Accident Date and Time	11/Jul/2024 5:45 PM
Accident Reported Date and Time	12/Jul/2024 11:58 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121823
Special Instruction to ARC,if any	DAMAGE TO THE LEFT REAR OF TAXI VEHICLE STILL IN TP COMPOUND 12/7/2024
Prepared Date and Time	2/Aug/2024 2:57 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,690.00	\$800.00
Total Spray Cost	\$1,856.00	\$700.00
Total Spare Part Cost	\$6,497.56	\$3,800.31
Total Other Cost	\$776.00	\$186.00
TOTAL COST	\$10,819.56	\$5,486.31 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	6.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN (LKK)
ARC / Surveyor Sign Off Date	07/08/2024 8:51 AM	06/08/2024 4:28 PM
Signature		
Remarks	P/P REPAIR / BEFORE PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR STEVE CHEN (LKK) / HP : 010-9429 541 / Email : stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-2408-0232	Invoice Number	
Quotation Date	22.08.2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$1,690.00	\$800.00
Total Labour	\$1,690.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR CHASSIS LH	\$220.00	\$0.00
TO RESPRAY REAR LH WHEEL HOUSE	\$220.00	\$100.00
TO RESPRAY FUEL LID COVER	\$220.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$220.00	\$100.00
TO RESPRAY REAR SKID PLATE	\$220.00	\$100.00
Total Spray Painting & Panel Beating	\$1,856.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$56.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$80.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$776.00	\$186.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87716G5000	CLIP-SIDE GARNISH MTG	0.00	\$1.15	0.00	\$0.00	Replace	Not Given
		87741G5000	GARNISH ASSY-QTR SIDE,LH	0.00	\$165.60	0.00	\$0.00	Replace	Not Given
		861792V000	CLIP	0.00	\$5.75	0.00	\$0.00	Replace	Not Given
		87830DB000	GARNISH ASSY-QTR FIXED,LH	0.00	\$424.35	0.00	\$0.00	Replace	Not Given

X
X
X
X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/08/2024
User ID : PohSuan

		87810DB020	GLASS & MOULDING ASSY-QUARTER FIXED,LH	0.00	\$108.10	0.00	\$0.00	Replace	Check	X
		87850DB000	GARNISH ASSY-C.PILLAR,LH	0.00	\$105.80	0.00	\$0.00	Replace	Not Given	X
		86613G5000	BRACKET ASSY-RR BUMPER SIDE,LH	1.00	\$28.75	10.00	\$25.88	Replace	Replace	√
		86663DB000	COVER-RR BUMPER FOG LAMP,LH	1.00	\$26.45	10.00	\$23.80	Replace	Replace	√
		86631DB000	BEAM-RR BUMPER	1.00	\$691.15	10.00	\$622.03	Replace	Replace	√
		86641DB000	STAY-RR BUMPER LH	0.00	\$67.85	0.00	\$0.00	Repair	Check	X
		86671DB000	SKID PLATE-RR BUMPER	1.00	\$120.75	10.00	\$108.67	Replace	Replace	√
		86681G5500	MOULDING ASSY-RR BUMPER SIDE,LH	1.00	\$17.25	10.00	\$15.53	Replace	Replace	√
		86695G5500	COVER-RR BUMPER SIDE UNDER,LH	1.00	\$13.80	10.00	\$12.42	Replace	Replace	√
		91880DB050	WIRING HARNESS-RR BUMPER	0.00	\$349.60	0.00	\$0.00	Replace	Not Given	X
		92405DB000	LAMP ASSY-BACK UP,LH	1.00	\$204.70	10.00	\$184.23	Replace	Replace	√
		99310S1900KCS	ULTRASONIC SENSOR-S.P.A.S	0.00	\$203.55	0.00	\$0.00	Replace	Not Given	X
		69100DB000	PANEL ASSY-BACK	0.00	\$604.90	0.00	\$0.00	Replace	Not Given	X
			CLIPS PIECE, RR BUMPER	10.00	\$4.80	10.00	\$43.20	Replace	Replace	√
		71503DBC10	PANEL ASSY-QUARTER OUTER,LH	1.00	\$1,388.05	10.00	\$1,249.24	Replace	Replace	√
		71550DB000	EXTENSION ASSY-QTR OTR RR LH	0.00	\$131.10	0.00	\$0.00	Replace	Not Given	X
		86821DB000	GUARD ASSY-REAR WHEEL,LH	1.00	\$293.25	10.00	\$263.93	Replace	Replace	√
			STICKER LOGO (RR FENDER)	1.00	\$50.00	0.00	\$50.00	Replace	Replace	√
		87130DB000	GARNISH ASSY-"D" PILLAR,LH	0.00	\$234.60	0.00	\$0.00	Replace	Not Given	X
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	√
		97510AA000	GRILLE ASSY-AIR EXTRACTOR	1.00	\$41.40	10.00	\$37.26	Replace	Replace	√
		86610DB000	COVER-RR BUMPER,UPR	1.00	\$615.25	10.00	\$553.73	Replace	Replace	√
		86612DB020	COVER-RR BUMPER LWR	1.00	\$637.10	10.00	\$573.39	Replace	Replace	√
Total					\$6,572.05		\$3,800.31			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3,800.31
+ 800.00
+ 886.00
5,486.31