

Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
CICS Limited Temasek Boulevard 10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		Mr Toh Hung Meng (zhao Hanming) 24 Sumang Walk #03-05 Singapore 828678 Mobile: 96300351		
			Document No.				
			0				
			Document Date				
			05/08/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAA10R	AWXBB S4	10/02/2021	SMY0533T	0	24851	77/ODUL/SMY0533T

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHY35BH802035124	M20AN257274	60	Cheng Wei Ting	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC24A00131100 ACC DATE:02/08/2024 TOW/DRIVE IN:02/08/2024 EXCESS:750.00\$ DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB3 TO CHECK WIRING AND CONDUCT WATER LEAK TEST				192.00
3	B	BP-LAB3 TO REMOVE AND REINSTALL FRONT BUMPER SENSOR TOENABLE FOR THE REPAIR				192.00
4	B	BP-ECU3 TO RESET ECU & REPROGRAMME				192.00
5	B	BP-MECH3 TO CONDUCT ADJUSTMENT ON FRONT PRE-COLLISION SENSORS				192.00
6	B	BP-MECH3 TO REPLACE TYRE RIM AND CONDUCT WHEEL BALANCING				192.00
7	B	BP-MECH3 TO CONDUCT ADJUSTMENT ON WHEEL ALIGNMENT				168.00
8	B	BP-LAB3 TO REPLACE AND REPAIR ON FRONT ACCIDENT AFFECTED AREA				1576 2304.00
9	B	BP-RES3 TO SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREA				1305 3284.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

o. Reg No. : 196700086Z

ST Reg No. : MR-8500000-9

No.2 Pandan Crescent

Singapore 128482, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Toh Hung Meng (zhao Hanming)
	Document No. 0	24 Sumang Walk #03-05 Singapore 828678
	Document Date 05/08/2024	Mobile: 96300351

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
------	-------	---------	-----------	----------	------------	---------	---------------------

2020	MZAA10R	AWXBB S4	10/02/2021	SMY0533T	0	24851	77/ODUL/SMY0533T
------	---------	----------	------------	----------	---	-------	------------------

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
-------------	------------	-------	--------------	------------	--------------

JTHY35BH802035124	M20AN257274	60	Cheng Wei Ting	--/--/----	0.00 --/--/---- 0.00
-------------------	-------------	----	----------------	------------	----------------------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	Z	BP-SLANT SUPPLY SEALANT (NETT) X ^{an}				100.00
11	1	L42611-76310 WHEEL, DISC ^{scr}	1.00	4002.80	30.00	✓ 2801.96
12	2	L52113-76902 EXTENSION, FR ^{repuv}	1.00	527.90	30.00	369.53
13	3	L89348-12140 B5 RETAINER, ULTRASONIC X ^{an}	1.00	57.90	30.00	40.53
14	4	L75895-53010 TAPE, MOULDING, NO.1 X ^{an}	2.00	55.50	30.00	77.70
15	5	L16563-24020 SEAL, RADIATOR TO X ^{an}	1.00	55.60	30.00	38.92
16	6	L52126-76050 BRACKET, FOG LAMP X ^{an}	1.00	84.10	30.00	58.87
17	7	L81482-76070 COVER, FOG LAMP, LH X ^{an}	1.00	189.20	30.00	132.44
18	8	L52411-76010 GUARD, FR BUMPER X ^{an}	1.00	537.10	30.00	375.97
19	9	L52116-76020 SUPPORT, FR BUMPER X ^{an}	1.00	120.60	30.00	84.42
20	0	L75392-35220 RETAINER, OUTSIDE ^{an}	4.00	5.60	30.00	✓ 15.68
21	1	L53802-76030 FENDER SUB-ASSY, FR X ^{an}	1.00	2035.50	30.00	1424.85
22	2	L75602-76010 MOULDING SUB-ASSY, ^{scr} photo EXCESS: TBA	1.00	506.50	30.00	✓ 354.55
23	3	T90467-07215 CLIP ^{an}	8.00	3.60	30.00	✓ 20.16
24	4	L90269-04051 RIVET ^{an}	10.00	2.20	30.00	✓ 15.40
25	5	T90269-06013 RIVET ^{an}	10.00	2.80	30.00	✓ 19.60

Rasul
 Hp 90010068
 5 days
 P/P
 07/08/24
 EXCESS: TBA
 Repair
 Reg after
 rejuv

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• To resurvey before/after drilling resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer's Signature

Charge Summary

Total 12,726.58

GST 9.00% 1,145.39

Parts 5,830.58

Labour 6,896.00

Sublet 0.00

Lubrication/Fluid 0.00

Others 0.00

Less 0.00

Amount Due 13,871.97