



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

Repair sum 6300

Not Authorised

Lm
Mora J
7/8/24
ins / fss

4 days

HP: 90096608

QUOTATION

QUOTATION FOR

NAME: Police Logistics Department
COMPANY NAME: Singapore Police Force
STREET ADDRESS: 1 Hemmant Road
POSTAL CODE: Singapore 438675
PHONE: -

DATE: 03/08/2024
REF: SLX6990J_310724
VEHICLE NO.: SLX6990J
MAKE: MERCEDES
MODEL: GLA180
PREPARED BY: RANDELL GOON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REPLACE FRONT BUMPER, FRONT REINFORCEMENT, LH FENDER, LH HEADLAMP & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT.	1		\$1,000.00		480	\$ 1,000.00
2	TO REPRAY FRONT BUMPER, FRONT LH FENDER, BLENDING FOR FRONT RH FENDER AND FRONT LH DOOR	1		\$800.00		600	\$ 800.00
3	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$150.00		11X	\$ 150.00
4	TO CARRY INSPECTION/CHECKS & TEST ON HANDBRAKE AND REAR BRAKE SYSTEM FOR DAMAGE	1		\$200.00		11X	\$ 200.00
5	TO TRANSFER THE FRONT BUMPER SENSORS	1		\$200.00		30	\$ 200.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$250.00		20	\$ 250.00
7	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$350.00		100	\$ 350.00
8	SUNDRIES	1		\$50.00		11X	\$ 50.00
PARTS							
1	FRONT BONNET	1		\$1,575.00	\$ 1,575.00	2X	\$ 1,575.00
2	FRONT BUMPER	1		\$1,400.00	\$ 1,400.00	Dis	\$ 1,400.00
3	FRONT BUMPER SPONGE	1		\$175.00	\$ 175.00	Torn	\$ 175.00
4	FRONT GRILLE	1		\$450.00	\$ 450.00	BVC	\$ 450.00
5	FRONT GRILLE LOGO	1		\$143.75	\$ 143.75	11	\$ 143.75
6	FRONT BUMPER LOWER TRIM GARNISH	1	1100	\$1,212.50	\$ 1,212.50	D.D	\$ 1,212.50
7	FRONT BUMPER LOWER TRIM GRILLE	1		\$193.75	\$ 193.75	Torn	\$ 193.75
8	FRONT BUMPER LH COVER	1		\$118.75	\$ 118.75	Torn	\$ 118.75
9	FRONT LH BUMPER SIDE BRACKET	1			\$ -	NS	\$ -
10	FRONT REINFORCEMENT BEAM	1		\$350.00	\$ 350.00	R	\$ 350.00
11	FRONT NUMBER PLATE HOLDER	1		\$150.00	\$ 150.00	11	\$ 150.00
12	FRONT LH HEADLAMP ASSY	1		\$2,812.50	\$ 2,812.50	CN	\$ 2,812.50

1102

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT	
13	FRONT LH HEADLAMP BRACKET	1			\$ -	NS	\$ -	X
14	FRONT LH SENSOR	1		\$212.50	\$ 212.50	BUL	\$ 212.50	X
15	FRONT LH SENSOR CORNER	1	102	\$175.00	\$ 175.00	BUL	\$ 175.00	X
16	FRONT LH FENDER TRIM	1		\$281.25	\$ 281.25	NT	\$ 281.25	X
17	FRONT LH FENDER	1		\$912.50	\$ 912.50	R	\$ 912.50	X
18	FRONT LH HORN	1		\$262.50	\$ 262.50	PN	\$ 262.50	X
19	FRONT BUMPER CLIPS	10	1 set	\$6.25	\$ 62.50	rec	\$ 62.50	30 S/N
20	RIVETS	10	1 set	\$6.25	\$ 62.50	rec	\$ 62.50	30 S/N
SUBTOTAL					\$ 10,550.00	SUBTOTAL	\$ 13,550.00	
GST 9%					\$ 949.50	GST 9%	\$ 1,219.50	
TOTAL					\$ 11,499.50	TOTAL	\$ 14,769.50	

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1-6407
- 102
P- 5766.30
S.N- 60
A- 1230
7056.30
102
6300



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

SUPPLEMENTARY

QUOTATION FOR

NAME: Police Logistics Department
COMPANY NAME: Singapore Police Force
STREET ADDRESS: 1 Hemmant Road
POSTAL CODE: Singapore 438675
PHONE:

DATE: 02/09/2024

REF: SLX6990J_310724
VEHICLE NO.: SLX6990J
MAKE: MERCEDES
MODEL: GLA180
PREPARED BY: RANDELL GOON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>PARTS</u>						
1	FRONT LH AIR FLOW SERRATION	1		\$189.00	\$ 189.00	7.11	\$ 189.00 ✓
2	BUMPER FRONT UPPER SUPPORT LH	1		\$52.50	\$ 53.00	0.19	\$ 53.00 ✓
3	BUMPER FRONT UNDERCOVER	1		\$ 365.00	\$ 365.00	7.01	\$ 365.00 ✓
102					SUBTOTAL	\$ 607.00	SUBTOTAL \$ 607.00
					GST 9%	\$ 54.63	GST 9% \$ 54.63
					TOTAL	\$ 661.63	TOTAL \$ 661.63

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD



(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)