

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24080098/KNP3E2**Date:** 30/10/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SKH4101T **Insured Vehicle No :** SMV8046X

Date of Loss: 03/08/2024 Nature of Claim: TP Claim No: DMPC2401018H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH4101T**

Make & Model: VOLKSWAGEN TOURAN SPORT, 1.4 TSI (A) Engine No: CTH003971

Reg. Date: 03/12/2012 (Man. Year: 2012) Chassis No: WVGZZZ1TZDW033281

Colour: Metallic Silver Odometer: 148771 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,527.04	3,032.93	1,494.11	33.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,030.00	1,580.00	60.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,137.04</b>	<b>4,062.93</b>	<b>3,074.11</b>	<b>43.07</b>
<b>+ GST 9.00/9.00% (\$\$)</b>	642.33	365.66	276.67	43.07
<b>Nett Amount (\$\$)</b>	<b>7,779.37</b>	<b>4,428.59</b>	<b>3,350.78</b>	<b>43.07</b>

INSPECTION

Date of Assignment: 06/08/2024

Date Inspected: 07/08/2024 Inspected At: Advantage VAG (HQ)  
160 Sin Ming Drive, #04-17 Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2024)
Parts:	M1-MPV	VOLKSWAGEN TOURAN SPORT 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH4101T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	447.85 FL	*447.85 FL
2	1		*FRONT FENDER BRACKET RH	Repair	54.08 FL	*- FL
3	1		*FRONT DOOR RH	Bent	1,815.32 FL	*1,692.80 FL
4	1		*FRONT DOOR CHROME MOULDING RH	Dented	202.80 FL	*202.80 FL
5	1		*FRONT DOOR HANDLE RH	Serviceable	168.45 FL	*- FL
6	1		*FRONT DOOR WEATHERSTRIP RH	Serviceable	236.69 FL	*- FL
7	1		*SIDE MIRROR ASSEMBLY RH	Serviceable	599.96 FL	*- FL
8	1		*SIDE MIRROR CAP RH	Serviceable	172.38 FL	*- FL
9	1		*FRONT WHEELHOUSE COVER RH	Serviceable	236.60 FL	*- FL
10	1		*SPORT RIM	Dented	1,026.47 FL	*1,026.47 FL
11	1		*SUNDRIES	Not Necessary	62.50 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,023.10	3,369.92
- List Item Discount on L Items 10.00/10.00% (\$\$)					496.06	336.99
Total Parts (\$\$)					4,527.04	3,032.93

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFITTING FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH AND EACH OTHER	New	1,280.00	400.00
2	SURFACE PREPARATION, SPRAY PAINT AND POLISH FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH AND OTHER AFFECTED AREAS	New	1,250.00	600.00
3	TO PERFORM DIAGNOSTIC CHECK	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,610.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >