



VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Vehicle Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Kenneth (C11616) Not Whorsh
96910883 24082.93
7/8/24 Penny After Paint 4 days

Date : 5-Aug-2024

Vehicle Num : SKH4101T

Make/Model : VOLKSWAGEN / TOURAN SPORT 1.4

Chassis No : WVGZZZ1TZDW033281

S/N	PARTS	QTY	PRICE	TOTAL
1	Front fender Rh	1	\$ B1 447.85	\$ ✓ 447.85
2	Front fender bracket Rh	1	\$ n 54.08	\$ X 54.08
3	Front door Rh 1692.80	1	\$ B1 1,815.32	\$ ✓ 1,815.32
4	Front door chrome molding Rh	1	\$ n 202.80	\$ ✓ 202.80
5	Front door handle Rh	1	\$ B1 168.45	\$ X 168.45
6	Front door wheathership Rh	1	\$ Sn 236.69	\$ X 236.69
7	Side mirror assembly Rh	1	\$ B1 599.96	\$ X 599.96
8	Side mirror cap Rh	1	\$ B1 172.38	\$ X 172.38
9	Front wheelhouse cover Rh	1	\$ B1 236.60	\$ X 236.60
10	Sport rim	1	\$ n 1,026.47	\$ ✓ 1,026.47
Total Parts				\$ 4,960.60
LESS 10%				\$ 496.06
TOTAL AMOUNT				\$ 4,464.54
MISCELLANEOUS ITEM				
1	Sunderies		\$ 62.50	
2				
LABOUR				
1	To remove and refitting front bumper, front fender Rh, front door Rh and each other.		\$ 1,280.00	40d
2	Surface preparation, spray paint and polish front bumper, front fender Rh, front door Rh and other affected areas.		\$ 1,250.00	60d
3	To perform diagnostic check		\$ 80.00	30d
TOTAL			\$ 2,672.50	\$ 7,137.04
GST 9%				\$ 642.33
GRAND TOTAL				\$ 7,779.37

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No negative workmanship is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: