



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24080099/Evp3e2
ACCIDENT CLAIMS SECTION	Date:	21/08/2024
(SPORE POLICE FORCE)		
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 3187Y	Veh. Inspected	SGR 88U
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/033 (LK)	Excess	\$0.00
Assign From	ENG CUI FEN	Assign Date	05/08/2024

### 2. Vehicle Details

Make & Model	VOLKSWAGEN SHARAN	C.C	1984
Engine No.	DED034374	Year of Reg.	16/10/2019
Chassis No.	WVWZZZ7NZKV018963	Colour	SILVER
Odometer	42235 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/50 R17	GOODYEAR	6
L/H Front Tyre	225/50 R17	GOODYEAR	6
R/H Rear Tyre	225/50 R17	GOODYEAR	6
L/H Rear Tyre	225/50 R17	GOODYEAR	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	02/08/2024	Inspection Date	06/08/2024
Survey held at	18 TEOW HOCK AVE S(545704) - OWNER RESIDENCE - REPAIRER: JIN AUTO SERVICES PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days