



Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: jin@jinauto.com.sg

Company Reg No: 200704370C , GST Reg No : 200704370C

03-08-24

M/S SPF

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR VOLKSWAGEN SHARAN - SGR88U

DOA : 02/08/2024

S/N	QTY	DESCRIPTION			
1	1 PC	REAR BUMPER DEF	\$	1677.31	1263 /
2	1 PC	REAR BUMPER SIDE RETAINER - RH x nn	\$	150.55	
3	1 PC	REAR BUMPER REVERSE SENSOR x nn	\$	467.92	
4	1 PC	REAR BUMPER RED REFLECTOR - RH BR	\$	137.55	/
5	1 PC	REAR RH TAIL LAMP BR	\$	999.31	867 /
6	1 PC	REAR RH FENDER x Repair	\$	REPAIR	
7	1 PC	REAR RH DOOR x Cut (Not consistent)	\$	REPAIR	
			\$	3432.64	2267.55
			\$	-343.26	-10%
			\$	3089.38	2040.79
8		SPRAY PAINTING	\$	1000.00	400
9		LABOUR CHARGE	\$	800.00	500
10		WIRING	\$	80.00	30
11		REAR RH RIM x NN (Not consistent)	\$	500.00	
			\$	5469.38	930

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Steve (LKK)
06/08/24, 10.00 am
Without Prejudice
3 days
Lump-sum
Resurvey After Spray

2970.79

L/S - 2376.63
= 2400



Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: jin@jinauto.com.sg

Company Reg No: 200704370C , GST Reg No : 200704370C

15-11-23

M/S INCOME LIMITED INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR () - ()

DOA : ()/()/()

S/N	QTY	DESCRIPTION
------------	------------	--------------------