

FIX AUTO PTE LTD

5 SOON LEE STREET # 01-61 (PIONEER POINT) SINGAPORE 627607

PEK KONG HWA
5 Soon Lee Street
01-61 (Pioneer Point)
Singapore 627607

3264.32

36.60

07th August 2024

45-\$3700/5days

1320.00

4614.32

20% - 3691.45

Accident date: 03rd August 2024

Estimated repair cost for vehicle no: SLU7143Y HONDA VEZEL 1.5 (COE DEC 2027)

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet X nn		\$1,150.00 X
2	1	Front bonnet lock X nn		\$188.00 X
3	1	Front head lamp -RH br /		\$1,785.00
4	1	Front head lamp lower bracket-RH X suc		\$122.00 X
5	1	Front bumper de /	765	\$890.00
6	1	Front bumper side bracket cut /	33.90	\$135.00
7	1	Front bumper clips-SET n /	30	\$60.00
8	1	Front bumper number plate X suc		\$100.00 X
9	1	Front bumper reinforcement bt /	398.50	\$582.00
10	1	Front bumper mud shield -RH cut /	116	\$185.00
11	1	Front bumper center lower garnish X suc		\$220.10 X
12	1	Front bumper center lower cover X suc		\$455.00 X
13	1	Front Bumper Fog lamp -RH ? cut /		\$215.00
14	1	Front Bumper Fog lamp cover-RH ? cut /	4490	\$155.00
15	1	Front Grille X suc		\$411.00 X
16	1	Front Grille emble logo X nn		\$100.00 X
17	1	Front Grille clips-SET X nn		\$65.00 X
18	1	Front fender-RH bt /	450	\$768.00
19	1	Front fender inner cowl -RH de -	168.20	\$188.00
20	1	Front R/H fender logo n /		\$58.80
21	1	front lower arm-RH X nn		\$388.00 X
22	1	Front knuckle arm-RH X nn		\$385.00 X
23	1	Front bearing-RH X nn		\$211.00 X
24	1	front shock absorber-RH X nn		\$512.00 X
25	1	front tyre -RH X nn		\$350.00 X
26	1	front rim -RH X nn		\$600.00 X

Subtotal :- \$10,383.90

Labour charges

To remove & re-fix front undercarriage -RH X nn

\$200.00 X

Wheel alignment (computer) X nn

\$150.00 X

To Check Wiring System

1320

30

\$80.00

40

\$120.00

nn X

\$100.00 ? receipt

\$800.00

\$800.00

Subtotal :-

\$2,230.00

Total:-

\$12,613.90

Tuff Kote

Towing charges

Panel beating

Spray painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4080.40

20%

3264.32

5/11-30

Repair

Hp 90010068

5 days

4/5

07/08/24

Repair after repair

550

700