

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: VOLVO S60 T2

Date: 07/08/2024

Engine/Chassis No.:

Claim Type: TP

Date of accident: 04.08.24

VRN: SLG9274M

Damaged area: Rear

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bootlid	1	\$ 2,113.00	\$ 2,113.00
2	Bootlid inner trim	1	\$ 519.00	\$ 519.00
3	Bootlid hinge	2	\$ 137.00	\$ 274.00
4	Bootlid lock	1	\$ 259.00	\$ 259.00
5	Bootlid lock striker	1	\$ 85.00	\$ 85.00
6	Bootlid lock release sensor	1	\$ 194.00	\$ 194.00
7	Bootlid release cable	1	\$ 53.00	\$ 53.00
8	Bootlid "VOLVO" emblem	1	\$ 81.00	\$ 81.00
9	Bootlid "S60" emblem	1	\$ 77.00	\$ 77.00
10	Bootlid "T2" emblem	1	\$ 72.00	\$ 72.00
11	Bootlid weatherstrip	1	\$ 185.00	\$ 185.00
12	Bootlid lamp	2	\$ 604.00	\$ 1,208.00
13	Bootlid lamp sponge seal	2	\$ 8.00	\$ 16.00
14	Rear bumper top bracket	4	\$ 72.00	\$ 288.00
15	Rear bumper tow cover	1	\$ 177.00	\$ 177.00
16	Rear bumper reinforcement	1	\$ 918.00	\$ 918.00
17	Rear bumper	1	\$ 1,863.00	\$ 1,863.00
18	Rear bumper lower diffuser	1	\$ 680.00	\$ 680.00
19	Rear bumper center	1	\$ 557.00	\$ 557.00
20	Taillamp lower bracket	2	\$ 105.00	\$ 210.00
21	Taillamp	2	\$ 889.00	\$ 1,778.00
22	Taillamp sponge seal	2	\$ 8.00	\$ 16.00
23	Taillamp panel	2	\$ 117.00	\$ 234.00
24	End panel top garnish	1	\$ 286.00	\$ 286.00
25	End panel	1	\$ 732.00	\$ 732.00
26	Spare tyre top board	1	\$ 389.00	\$ 389.00
27	Spare tyre floor panel	1	\$ 998.00	\$ 998.00
			Subtotal	\$ 14,262.00
			List discount	10.00%
			Total	\$ 12,835.80

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Sundries	1	\$ 50.00	\$ 50.00
2	Reverse sensor (Factory original)	2	\$ 464.00	\$ 928.00
3	Bootlid inner trim clips	10	\$ 6.50	\$ 65.00

Repair Estimate

4	Rear bumper clips	10	\$ 6.50	\$ 65.00
5	Taillamp clips	6	\$ 6.50	\$ 39.00
6	Bootlid lamp clips	6	\$ 6.50	\$ 39.00
7	End panel sealant	1	\$ 100.00	\$ 100.00
8	End panel top garnish clips	6	\$ 6.50	\$ 39.00
9	Spare tyre floor panel sealant	1	\$ 100.00	\$ 100.00
10	Rear fender inner trim clips	16	\$ 6.50	\$ 104.00
11	Rear licence plate & frame	1	\$ 55.00	\$ 55.00
			Total	\$ 1,584.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	7	\$ 1,400.00
5	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 3,050.00

Estimate Grand Total	\$ 17,469.80
-----------------------------	---------------------