

Co. Reg No. : 196700086Z
GST Reg No. : MR-8600000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6831 1188

ESTIMATE

Account Details		Customer Details	
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	Account No.	Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607	
	S1000005 / ICFIC1		
	Document No. 0		
	Document Date 05/08/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
JTMV43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI TP INS:First Capital Insurance Ltd TP VEH:SHB2182P DATE OF ACC:04.08.2024				50 100.00
2	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP				134.64
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR				198.00
5	S	BP-SUBLET SUPPLY NO PLATE - FRONT & BACK				160.00
6	B	BP-LAB2 REPLACE ACC DAMAGED PARTS - FRONT				2376.00
7	B	BP-RES2 RESPRAY ACC AFFECTED AREAS - FRONT				1968.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT) - REAR				300.00
9	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR -R EAR				198.00
10	B	BP-LAB2 CHECK WIRING SYSTEM				134.64
11	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE. R/I REAR REVERSE CAMERA TO FAC REPAIR.				540.00
12	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR - REAR				396 702.00
13	B	BP-WS2 REPLACE TAILGATE GLASS				594.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary	Total
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Borneo Motors



TOYOTA

choape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept				S1000005 / ICFIC1		Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607			
				Document No. 0					
				Document Date 05/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTMV43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
14	S	BP-SUBLET SUPPLY SOLAR FILM							480.00
15	S	BP-SUBLET REPLACE KICK SENSOR							198.00
16	B	BP-MECH2 REPLACE REAR EXHAUST PIPE SYSTEM							792.00
17	B	BP-LAB2 REPLACE ACC DAMAGED PARTS - REAR							636.00
18	B	BP-RES2 RESPRAY ACC AFFECTED AREAS - REAR							5248.00
19	Z	BP-SUNDRY SUPPLY REAR BUMPER TOP CHROME							380.00
20	1	T52119-4A916 COVER, FR BUMPER				1.00	636.90		636.90
21	2	T52437-42901 COVER, FR BUMPER				1.00	27.10		27.10
22	3	T52438-42901 COVER, FR BUMPER				1.00	27.10		27.10
23	4	T53285-42120 COVER, FR BUMPER ARM				1.00	25.10		25.10
24	5	T53286-42130 COVER, FR BUMPER ARM				1.00	25.10		25.10
25	6	T53113-42121 GRILLE, RADIATOR, cut				1.00	395.50		395.50
26	7	T52114-42150 BRACKET, FR BUMPER				1.00	110.80		110.80
27	8	T52411-42110 GUARD, FR BUMPER				1.00	502.70		502.70
28	9	T52711-42140 B0 MOULDING, FR BUMPER				1.00	661.60		661.60
29	0	S52161-0K040 PIECE, RR BUMPER				10.00	5.80		58.00
30	1	T53395-42080 SEAL, HOOD TO FR END				1.00	118.50		118.50
31	2	T52535-42050 RETAINER, FR BUMPER				1.00	150.50		150.50
32	3	T52536-42080 RETAINER, FR BUMPER				1.00	150.50		150.50
33	4	T90467-07215 CLIP				10.00	3.60		36.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Borneo Motors



Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Customer Details	
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	Account No.	Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607	
	S1000005 / ICFIC1		
	Document No.		
	0		
	Document Date		
	05/08/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
JTMV43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	5	T52614-42120 ABSORBER, FR BUMPER ? Xan	1.00	124.50		124.50
35	6	T52021-42200 REINFORCEMENT ? Xan	1.00	1061.60		1061.60
36	7	T53141-33130 GARNISH, RADIATOR Xan	1.00	1091.60		1091.60
37	8	T53112-42190 GRILLE, RADIATOR, ? Xan	1.00	443.50		443.50
38	9	T53123-42020 MOULDING, RADIATOR Xan	1.00	60.70		60.70
39	0	T53124-42060 MOULDING, RADIATOR Xan	1.00	60.70		60.70
40	1	T53115-42010 BRACKET, RADIATOR ? Xan	1.00	458.90		458.90
41	2	T53510-42150 LOCK ASSY, HOOD Xan	1.00	188.00		188.00
42	3	T53019-42020 SHUTTER SUB-ASSY, ? Xan	1.00	457.70		457.70
43	4	T16681-25010 PLATE, RADIATOR UPR ? Xan	1.00	154.80		154.80
44	5	T90467-10216 CLIP ? Xan	10.00	4.80		48.00
45	6	T16594-25020 GUIDE, RADIATOR AIR, ? Xan	1.00	87.50		87.50
46	7	T16593-25110 GUIDE, RADIATOR AIR, ? Xan	1.00	137.10		137.10
47	8	T16595-25120 GUIDE, RADIATOR AIR, ? Xan	1.00	122.10		122.10
48	9	T81145-42A23 UNIT, HEADLAMP ? Xan	1.00	5536.60		5536.60
49	0	T81185-42A23 UNIT, HEADLAMP cm	1.00	5536.60		5536.60
50	1	SPC507-42001 RAV4 BACK SENSOR RES an	1.00	221.80		221.80
51	2	T51931-42030 CARRIER, SPARE WHEEL ? Xan	1.00	28.70		28.70
52	3	T64777-42071 CUSHION, SPARE WHEEL ? Xan	1.00	273.50		273.50
53	4	T52159-42230 COVER, RR BUMPER de	1.00	480.20		480.20

For & on behalf of				
Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary		Total
	Please acknowledge receipt of vehicle	Parts		Less Amount Due
		Labour		
		Sublet		
		Lubrication/Fluid		
		Others		



Reg No. : 196700086Z
 SST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept				S1000005 / ICFIC1		Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607			
				Document No. 0					
				Document Date 05/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTMV43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
54	5	S52161-0K040 PIECE, RR BUMPER <i>m</i>				10.00	5.80		✓ 58.00
55	6	T52453-42040 B0 GUARD, RR BUMPER <i>m</i>				1.00	901.50		✓ 901.50
56	7	L75392-35220 RETAINER, OUTSIDE <i>m</i>				4.00	5.60		✓ 22.40
57	8	T52161-42944 PIECE, RR BUMPER, RH <i>xan</i>				1.00	472.20		✓ 472.20
58	9	T52162-42944 PIECE, RR BUMPER, LH <i>xan</i>				1.00	472.20		✓ 472.20
59	0	T52155-42050 SUPPORT, RR BUMPER <i>xan</i>				1.00	112.50		✓ 112.50
60	1	T52562-42060 RETAINER, RR BUMPER <i>xan</i>				1.00	150.50		✓ 150.50
61	2	T52156-42050 SUPPORT, RR BUMPER <i>m</i>				1.00	112.50		✓ 112.50
62	3	T52563-42050 RETAINER, RR BUMPER <i>m</i>				1.00	150.50		✓ 150.50
63	4	T52023-42060 REINFORCEMENT <i>bf</i>				1.00	551.50		✓ 551.50
64	5	T891B1-42030 BRACKET, KICK DOOR <i>cm</i>				1.00	205.20		✓ 205.20
65	6	T891B2-0W050 SENSOR, KICK DOOR <i>cm</i>				1.00	768.30		✓ 768.30
66	7	T89747-30040 BUZZER, WIRELESS <i>xan</i>				1.00	187.50		✓ 187.50
67	8	T31364-42020 WIRE, CLUTCH CONTROL <i>xan</i>				1.00	186.40		✓ 186.40
68	9	T58307-42080 PANEL SUB-ASSY, BODY <i>bf</i>				1.00	1058.90		✓ 1058.90
69	0	T58301-42902 PAN SUB-ASSY, RR <i>bf</i>				1.00	886.30		✓ 886.30
70	1	T58327-42030 INSULATOR, MAIN <i>bf</i>				1.00	233.90		✓ 233.90
71	2	T64730-42221 C0 PANEL ASSY, DECK <i>bf</i>				1.00	870.90		✓ 870.90
72	3	T64740-42161 C0 PANEL ASSY, DECK <i>xan</i>				1.00	825.10		✓ 825.10
73	4	T58387-42130 C0 PLATE, RR FLOOR <i>bf</i>				1.00	334.70		✓ 334.70

For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary	Total
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Borneo Motors



TOYOTA

Reg No. : 196700086Z
 SST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept				S1000005 / ICFIC1		Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607			
				Document No.					
				0					
				Document Date					
				05/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTMV43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----	0.00	--/--/----		0.00
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
74	5	T58410-42120 C1 BOARD ASSY, DECK <i>? xan</i>			1.00	1034.30		1034.30	
75	6	T58416-42070 C0 BOARD, RR FLOOR, <i>? xan</i>			1.00	207.00		207.00	
76	7	T58417-42070 C0 BOARD, RR FLOOR, <i>? xan</i>			1.00	207.00		207.00	
77	8	T58577-42150 C0 PLATE, RR FLOOR MAT <i>? xan</i>			1.00	645.40		645.40	
78	9	T64779-42050 STOPPER, SPARE WHEEL <i>? xan</i>			1.00	248.40		248.40	
79	0	T67005-42650 PANEL SUB-ASSY, BACK <i>bt</i>			1.00	3113.60		3113.60	
80	1	T67881-42070 WEATHERSTRIP, BACK <i>xan</i>			1.00	465.30		465.30	
81	2	T68105-42300 GLASS SUB-ASSY, BACK <i>ne / plate</i>			1.00	1706.50		1706.50	
82	3	T62785-60030 SPACER, QUARTER <i>ne</i>			2.00	8.20		16.40	
83	4	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>ne</i>			2.00	108.00		216.00	
84	5	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>ne</i>			1.00	200.00		200.00	
85	6	T76802-42140 GARNISH SUB-ASSY, <i>ne</i>			1.00	332.40		332.40	
86	7	T67750-42060 C0 BOARD ASSY, BACK <i>xan</i>			1.00	647.90		647.90	
87	8	T69350-42080 LOCK ASSY, BACK DOOR <i>xan</i>			1.00	1100.10		1100.10	
88	9	T75431-42180 EMBLEM, BACK DOOR, <i>ne</i>			1.00	75.70		75.70	
89	0	T75606-42150 MOULDING SUB-ASSY, <i>de</i>			1.00	154.40		154.40	
90	1	T90467-07215 CLIP <i>ne</i>			1.00	3.60		3.60	
91	2	T81551-42230 LENS & BODY, RR <i>xan</i>			1.00	748.10		748.10	
92	3	T81561-42230 LENS & BODY, RR <i>? xan</i>			1.00	748.10		748.10	
93	4	S81910-0K030 REFLECTOR ASSY, REFL <i>? xan</i>			1.00	91.80		91.80	

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Borneo Motors



TOYOTA

No. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mr Han Choon Poo			
			Document No. 0		62 Jalan Binchang			
			Document Date 05/08/2024		Singapore 573952 Mobile: 96350607			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTMY43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
94	5	S81920-0K010 REFLECTOR ASSY, REFL <i>? X n</i>			1.00	91.80		91.80
95	6	T89997-30100 ANTENNA, ELECTRICAL <i>? X n</i>			1.00	100.00		100.00
96	7	T17408-25042 BAFFLE SUB-ASSY, <i>? X n</i>			2.00	217.60		435.20
97	8	T17430-25221 PIPE ASSY, EXHAUST <i>? X n</i>			1.00	2436.70		2436.70
98	9	T17565-28010 SUPPORT, EXHAUST <i>? X n</i>			1.00	68.20		68.20
99	0	T17577-25010 BRACKET, EXHAUST <i>? X n</i>			1.00	76.60		76.60
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: <i>Rasul</i> <i>4p 90010068</i> <i>12 days</i> <i>07/08/2024</i> <i>Res by paint</i>								
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							64,390.68	
			Please acknowledge receipt of vehicle				GST 9.00%	
					Parts 43,263.40 Labour 20,289.28 Sublet 838.00 Lubrication/Fluid 0.00 Others 0.00		5,795.16	
					Less		0.00	
					Amount Due		70,185.84	



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No. S1000005 / ICFIC1		Customer Details				
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		Document No. 0		Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607				
		Document Date 03/09/2024						
		Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTMV43FV40D056477		M20AV213491	60	Thomas Pang W T	07/08/2024 8.00		08/08/2024 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	1	T17410-24270 PIPE ASSY, EXHAUST, <i>ht</i>			1.00	3875.80		3875.80
2	2	T90917-06094 GASKET, EXHAUST PIPE <i>na</i>			1.00	34.50		34.50
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 3,910.30		
		Please acknowledge receipt of vehicle		Parts 3,910.30		GST 9.00% 351.93		
				Labour 0.00				
				Sublet 0.00				
				Lubrication/Fluid 0.00		Less 0.00		
				Others 0.00		Amount Due 4,262.23		

Customer Copy