



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24080106/Enh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	22/08/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 2419Z	Veh. Inspected	SGN 7961Z
Policy No.	-	Coverage	0
Claim No.	AVS24/2520	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	06/08/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS 1.6 AUTO	C.C	1598
Engine No.	3ZZ4615652	Year of Reg.	28/11/2006
Chassis No.	MR053ZEC107135625	Colour	BLACK
Odometer	172814 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/70R14	GRENLANDER	5
L/H Front Tyre	185/70R14	GRENLANDER	5
R/H Rear Tyre	185/70R14	GRENLANDER	5
L/H Rear Tyre	185/70R14	GRENLANDER	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2024	Inspection Date	08/08/2024
Survey held at	FIRST GARAGE PTE LTD - 13 KAKI BUKIT ROAD 4, #03-30 BARTLEY BIZ CENTRE, SINGAPORE 417807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days