

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080112/RPA3Q2
Date: 14/10/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_05
Claimant Vehicle No : SHB2324Y Insured Vehicle No : SNF3923U
Date of Loss: 06/08/2024 Nature of Claim: TP Claim No: MFL2024D0009176

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB2324Y
Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS064167
Reg. Date: 28/09/2017 (Man. Year: 2017) Chassis No: JTDKB3FUX03564302
Colour: Yellow Odometer: 820721 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm
Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,054.87	3,172.97	3,881.90	55.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	1,320.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,374.87	4,492.97	3,881.90	46.35
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	8,374.87	3,600.00	4,774.87	57.01
+ GST 9.00/9.00% (S\$)	753.74	324.00	429.74	57.01
Nett Amount (S\$)	9,128.61	3,924.00	5,204.61	57.01
+ Car Rental (7.0 x S\$105.48/day) (S\$)		738.36		
+ Loss of Earnings (7.0 x S\$40.00/day) (S\$)		280.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,944.54		

INSPECTION

Date of Assignment: 07/08/2024
Date Inspected: 07/08/2024 Inspected At: Ding Automotive Pte Ltd (HQ)
31 CORPORATION ROAD
Singapore 649825
Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2024)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB2324Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	442.60 FL	*442.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	332.70 FL	*332.70 FL
3	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	126.30 FL	*- FL
4	1		*REAR BUMPER DIFFUSER	Scratched	576.30 FL	*576.30 FL
5	1		*REAR BUMPER RETAINER LH	Scratched	117.70 FL	*117.70 FL
6	1		*REAR BUMPER UNDER COVER LH	Not Necessary	241.90 FL	*- FL
7	1		*REAR BUMPER UNDER COVER CENTER	Not Necessary	229.90 FL	*- FL
8	1		*SEAL REAR BUMPER SIDE LH	Not Necessary	88.50 FL	*- FL
9	1		*REAR BUMPER EXTENSION DIFFUSER LH	Not Necessary	123.70 FL	*- FL
10	1		*BOX DECK FLOOR LH	Not Necessary	313.60 FL	*- FL
11	1		*TAILLAMP UPPER LH	Cracked	443.30 FL	*443.30 FL
12	1		*TAILLAMP LOWER LH	Cracked	502.00 FL	*502.00 FL
13	1		*TAILLAMP LOWER LED BULB LH (STOP LAMP)	Not Necessary	90.50 FL	*- FL
14	1		*TAILLAMP LOWER LED BULB LH (FOG LAMP)	Not Necessary	94.80 FL	*- FL
15	1		*TAILGATE	Not Necessary	1,147.80 FL	*- FL
16	1		*TAILGATE HINGE LH	Not Necessary	61.00 FL	*- FL
17	1		*TAILGATE HINGE RH	Not Necessary	61.00 FL	*- FL
18	1		*TAILGATE OUTER GARNISH	Scratched	925.60 FL	*925.60 FL
19	1		*TAILGATE EMBLEM -HYBRID	Necessary	54.60 FL	*54.60 FL
20	1		*TAILGATE EMBLEM -TOYOTA LOGO	Necessary	47.90 FL	*47.90 FL
21	1		*TAILGATE EMBLEM -PRIUS	Necessary	54.60 FL	*54.60 FL
22	1		*REAR BUMPER SMART KEY ANTENNA	Not Necessary	72.00 FL	*- FL
23	1		*REAR END PANEL	Not Necessary	650.30 FL	*- FL
24	1		*TAILLAMP PANEL LH	Not Necessary	103.40 FL	*- FL
25	1		*TAILLAMP COVER LH	Not Necessary	64.50 FL	*- FL
26	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
27	1		*SET REAR BUMPER UNDER COVER CLIP	Not Necessary	45.00 FS	*- FS
28	1		*SET REAR BUMPER EXTENSION DIFFUSER LH CLIP	Not Necessary	35.00 FS	*- FS
29	1		*REAR BUMPER ADS STICKER	Necessary	250.00 FS	*150.00 FS
30	1		*SET REAR REVERSE SENSOR	Not Necessary	230.00 FS	*- FS
31	1		*REAR FENDER ADS STICKER LH	Necessary	250.00 FS	*150.00 FS
32	1		*REAR FENDER ADS STICKER RH	Not Necessary	250.00 FS	*- FS
33	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN UPPER PRIMED	Not Necessary	20.00 FS	*- FS
35	1		*TAILGATE WINDSCREEN UPPER SEALANT	Not Necessary	60.00 FS	*- FS
36	1		*TAILGATE WINDSCREEN LOWER PRIMER	Not Necessary	20.00 FS	*- FS
37	1		*TAILGATE WINDSCREEN LOWER SEALANT	Not Necessary	60.00 FS	*- FS
38	1		*TAILGATE STICKER -ZIG LOGO & BOOK NOW	Necessary	150.00 FS	*100.00 FS
39	1		*TAILGATE STICKER -COMFORT DELGRO & 65521111	Necessary	150.00 FS	*100.00 FS
40	1		*REAR FENDER STICKER -PETROL ONLY	Not Necessary	120.00 FS	*- FS
41	1		*TAILLAMP PANEL SEALANT LH	Not Necessary	60.00 FS	*- FS
42	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
43	1		*REAR FENDER SEALANT RH (NPA)	Not Necessary	0.00 FS	*- FS
44	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 8,796.50 4,047.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					1,741.63	874.33
Total Parts (S\$)					7,054.87	3,172.97
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHT AND PANEL BEAT ACCIDENT AREA	New	600.00	600.00
2	RUST PROOFING (NPA)	New	0.00	0.00
3	DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	New	80.00	80.00
4	R&R SPARE TYRE & CARPET & TRIM & BOARD (NPA)	New	0.00	0.00
5	R&R REVERSE SENSOR	New	40.00	40.00
6	R&R TAILGATE COMPONENTS (NPA)	New	0.00	0.00
7	R&R TAILGATE WINDSCREEN UPPER & LOWER (NPA)	New	0.00	0.00
8	R&R TAILGATE SPOILER (NPA)	New	0.00	0.00
9	RESPRAY REAR BUMPER	New	200.00	200.00
10	RESPRAY REAR BUMPER EXTENSION DIFFUSER LH (NPA)	New	0.00	0.00
11	RESPRAY REAR BUMPER DIFFUSER (NPA)	New	0.00	0.00
12	RESPRAY REAR END PANEL (NPA)	New	0.00	0.00
13	RESPRAY REAR FENDER LH	New	200.00	200.00
14	RESPRAY REAR FENDER RH (NPA)	New	0.00	0.00
15	RESPRAY TAILGATE (NPA)	New	0.00	0.00
16	RESPRAY TAILGATE OUTER GARNISH	New	200.00	200.00
17	RESPRAY TAILGATE HINGE LH & RH (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			1,320.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >