

(08/11/13) wef
ASS. REC. BY:

REF:

CD/1124080112/Rpa3

8396

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB 23244

at Workshop m/s

DINH ANU

of

CORPORATION RS

Insured:

111

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

14K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 5.5

Veh No:

SHB23244

Yr Regn:

2017 / 86P

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS HYBRID 1.8 CVT c.c. 1798

Colour

YELLOW

AC:

Insured / Std / NI / NA

Sp. Reading

820721

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU03564302

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

06/08/24

D.O.I.

07/08/24

Survey held at

CORPORATION RS

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

REAR N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) \$ + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

06/08/2024 15:52

JOB-NO: 50116290

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB2324Y

TRANS: AUTO

CHASSIS: JTDKB3FUX03564302

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZRS064167

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	0.00	0.00	0.00	Y		600
2 RUST PROOFING	1.00	0.00	0.00	0.00	Y		X
3 SUNDRIES	1.00	0.00	0.00	0.00	Y		20
4 DIAGNOSTIC(CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	1.00	0.00	0.00	0.00	Y		80
5 R&R SPARE TYRE & CARPET & TRIM & BOARD	1.00	0.00	0.00	0.00	Y		X
6 R&R REVERSE SENSOR	1.00	0.00	0.00	0.00	Y		40
7 R&R TAILGATE COMPONENTS	1.00	0.00	0.00	0.00	Y		X
8 R&R TAILGATE WINDSCREEN UPPER & LOWER	1.00	0.00	0.00	0.00	Y		X
9 R&R TAILGATE SPOILER	1.00	0.00	0.00	0.00	Y		X
10 RESPRAY REAR BUMPER	1.00	0.00	0.00	0.00	Y		200
11 RESPRAY REAR BUMPER EXTENSION DIFFUSER LH	1.00	0.00	0.00	0.00	Y		X
12 RESPRAY REAR BUMPER DIFFUSER	1.00	0.00	0.00	0.00	Y		X
13 RESPRAY REAR END PANEL	1.00	0.00	0.00	0.00	Y		X
14 RESPRAY REAR FENDER LH	1.00	0.00	0.00	0.00	Y		200
15 RESPRAY REAR FENDER RH	1.00	0.00	0.00	0.00	Y		X
16 RESPRAY TAILGATE	1.00	0.00	0.00	0.00	Y		X
17 RESPRAY TAILGATE OUTER GARNISH	1.00	0.00	0.00	0.00	Y		200
18 RESPRAY TAILGATE HINGE LH & RH	1.00	0.00	0.00	0.00	Y		X
TOTAL:		0.00	0.00	0.00			
MATERIALS							
1 REAR BUMPER <i>de</i>	1.00	442.60	110.65	331.95	L	Y	
2 REAR BUMPER REINFORCEMENT <i>bl</i>	1.00	332.70	83.18	249.52	L	Y	
3 REAR BUMPER REINFORCEMENT BRACKET LH <i>2X</i>	1.00	126.30	31.58	94.72	L	Y	
4 REAR BUMPER DIFFUSER <i>scu</i>	1.00	576.30	144.08	432.22	L	Y	
5 REAR BUMPER RETAINER LH <i>scu</i>	1.00	117.70	29.43	88.27	L	Y	
6 REAR BUMPER UNDER COVER LH <i>X</i>	1.00	241.90	60.48	181.42	L	Y	
7 REAR BUMPER UNDER COVER CENTER <i>X</i>	1.00	229.90	57.48	172.42	L	Y	
8 SEAL,REAR BUMPER SIDE,LH <i>X</i>	1.00	88.50	22.13	66.37	L	Y	
9 REAR BUMPER EXTENSION DIFFUSER LH <i>X</i>	1.00	123.70	30.93	92.77	L	Y	
10 BOX,DECK FLOOR,LH <i>X</i>	1.00	313.60	78.40	235.20	L	Y	
11 TAILLAMP UPPER LH <i>crn</i>	1.00	443.30	110.83	332.47	L	Y	
12 TAILLAMP LOWER LH <i>crn</i>	1.00	502.00	125.50	376.50	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
13 TAILLAMP LOWER LED BULB LH (STOP LAMP) <i>X</i>	1.00	90.50	22.63	67.87	L	Y	
14 TAILLAMP LOWER LED BULB LH (FOG LAMP) <i>X</i>	1.00	94.80	23.70	71.10	L	Y	
15 TAILGATE	1.00	1,147.80	286.95	860.85	L	Y	
16 TAILGATE HINGE LH <i>X</i>	1.00	61.00	15.25	45.75	L	Y	
17 TAILGATE HINGE RH <i>X</i>	1.00	61.00	15.25	45.75	L	Y	
18 TAILGATE OUTER GARNISH <i>sur</i>	1.00	925.60	231.40	694.20	L	Y	
19 TAILGATE EMBLEM - HYBRID <i>m</i>	1.00	54.60	13.65	40.95	L	Y	
20 TAILGATE EMBLEM - TOYOTA LOGO <i>m</i>	1.00	47.90	11.98	35.92	L	Y	
21 TAILGATE EMBLEM - PRIUS <i>m</i>	1.00	54.60	13.65	40.95	L	Y	
22 REAR BUMPER SMART KEY ANTENNA <i>X</i>	1.00	72.00	18.00	54.00	L	Y	
23 REAR END PANEL <i>X</i>	1.00	650.30	162.58	487.72	L	Y	
24 TAILLAMP PANEL LH <i>X</i>	1.00	103.40	25.85	77.55	L	Y	
25 TAILLAMP COVER LH <i>X</i>	1.00	64.50	16.13	48.37	L	Y	
26 REAR BUMPER CLIP SET <i>m</i>	1.00	50.00	0.00	50.00 <i>30</i>	S	Y	
27 REAR BUMPER UNDER COVER CLIP SET <i>X</i>	1.00	45.00	0.00	45.00	S	Y	
28 REAR BUMPER EXTENSION DIFFUSER LH CLIP SET <i>X</i>	1.00	35.00	0.00	35.00	S	Y	
29 REAR BUMPER ADS STICKER <i>m</i>	1.00	250.00	0.00	250.00 <i>150</i>	S	Y	
30 REAR REVERSE SENSOR SET <i>X</i>	1.00	230.00	0.00	230.00 <i>X</i>	S	Y	
31 REAR FENDER ADS STICKER LH <i>m</i>	1.00	250.00	0.00	250.00 <i>150</i>	S	Y	
32 REAR FENDER ADS STICKER RH <i>X</i>	1.00	250.00	0.00	250.00 <i>X</i>	S	Y	
33 REAR END PANEL SEALANT <i>X</i>	1.00	60.00	0.00	60.00 <i>X</i>	S	Y	
34 TAILGATE WINDSCREEN UPPER PRIMER <i>X</i>	1.00	20.00	0.00	20.00 <i>X</i>	S	Y	
35 TAILGATE WINDSCREEN UPPER SEALANT <i>X</i>	1.00	60.00	0.00	60.00 <i>X</i>	S	Y	
36 TAILGATE WINDSCREEN LOWER PRIMER <i>X</i>	1.00	20.00	0.00	20.00 <i>X</i>	S	Y	
37 TAILGATE WINDSCREEN LOWER SEALANT <i>X</i>	1.00	60.00	0.00	60.00 <i>X</i>	S	Y	
38 TAILGATE STICKER - ZIG LOGO & BOOK NOW <i>m</i>	1.00	150.00	0.00	150.00 <i>100</i>	S	Y	
39 TAILGATE STICKER - COMFORT DELGRO & 65521111 <i>m</i>	1.00	150.00	0.00	150.00 <i>100</i>	S	Y	
40 REAR FENDER STICKER - PETROL ONLY <i>X</i>	1.00	120.00	0.00	120.00 <i>X</i>	S	Y	
41 TAILLAMP PANEL SEALANT LH <i>X</i>	1.00	60.00	0.00	60.00 <i>X</i>	S	Y	
TOTAL:		8,776.50	1,741.69	7,034.81			
42 Rear fender RH repair							
TOTAL PARTS & LABOUR:		8,776.50	1,741.69	7,034.81			
43 Rear fender sealant RH <i>X</i>							
EXCESS/LOADING:S\$		0.00					

No. Of Day:

*6 days*RE-SURVEY: BEFORE AFTER PAINTING
PART-BY-PART OR LUMP SUM S\$DATE OF SURVEY: *07 / 08 / 24*SURVEYED BY: *PRM*CONTACT NO: *90010068*

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
60190078

Ding Auto User 1

ESTIMATOR

STAAUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: