

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 05.08.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBD8534D**
MODEL : **TOYOTA DYNA**
DATE OF ACCIDENT : 29.06.2024
TIME OF ACCIDENT : 17:40 HOURS

Hui Rong.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,950.00	\$ 1,950.00
2	TAILGATE 'TOYOTA' STICKER <i>new</i>	1	\$ 138.10	\$ 138.10
3	TAILGATE HINGE <i>1 piece bent</i>	4	\$ 185.00	\$ 740.00
4	TAILGATE SIDE LOCK <i>new</i>	2	\$ 180.00	\$ 360.00
5	TAILGATE STOPPER RUBBER RH <i>3 x 4</i>	1	\$ 35.00	\$ 35.00
6	TAILGATE STOPPER BRACKET RH <i>1 x 2</i>	1	\$ 175.00	\$ 175.00
7	TAILGATE SAFETY LOCK RH	2	\$ 145.00	\$ 290.00
8	TAIL LAMP RH <i>lit</i>	1	\$ 298.10	\$ 298.10
9	TAIL LAMP SUPPORT BRACKET RH <i>new</i>	1	\$ 185.00	\$ 185.00
10	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 85.00	\$ 170.00
11	REAR NUMBER PLATE SUPPORT BRACKET <i>new</i>	1	\$ 195.00	\$ 195.00
12	REAR END PANEL <i>Repair</i>	1	\$ 1,690.00	\$ 1,690.00

1933.10 TOTAL PRICE \$ 6,226.20
1445.82 LESS 25% \$ 1,556.55
SUB TOTAL PRICE \$ 4,669.65

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00
2	REAR STEP BRACKET (SPECIAL TYPE) <i>new</i>	1	\$ 250.00	\$ 250.00
3	TAIL GATE '70KM/H' STICKER <i>New</i>	1	\$ 40.00	\$ 40.00
4	TAIL GATE '13PAX' STICKER <i>new</i>	1	\$ 40.00	\$ 40.00

TO : INCOME MOTOR CLAIMS DEPTS
VEHICLE NO : GBD8534D
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 29.06.2024
TIME OF ACCIDENT : 17:40 HOURS

5	TAIL GATE COVER (ALUMINIUM) (SPECIAL TYPE)	1	\$ 800.00	\$ 800.00
6	REAR FLOOR TOP BOARD (ALUMINIUM) (SPECIAL TYPE)	1	\$ 1,800.00	\$ 1,800.00
7	REVERSE SENSOR (SET)	1	\$ 220.00	\$ 220.00

65 TOTAL \$ 3,200.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,800.00	300
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	300
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	x
4	REMOVE AND REFIX TAIL GATE COVER	\$ 120.00	x
5	REMOVE&REFIX FLOOR PANEL TOP BOARD (ALUMINIUM)	\$ 450.00	x

TOTAL \$ 3,850.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,869.65
TOTAL LABOUR COST : \$ 3,850.00
TOTAL REPAIR COST : \$ 11,719.65

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Admin
1/s 07/08/24
02 Days
Total: 2114.82
1/s 1.7K
1.7K