

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 9167A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,455.20	1,080.00
2	REAR BUMPER SIDE RETAINER @\$62.40	NOT NECESSARY	124.80	-
2	REAR BUMPER REFLECTOR @\$90.00	NOT NECESSARY	180.00	-
1	REAR BUMPER REINFORCEMENT	DENTED	410.00	410.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	80.00	-
2	REAR BUMPER REVERSE SENSOR @\$280.00	NOT NECESSARY	560.00	-
1	REAR END PANEL	NOT NECESSARY	670.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	190.00	-
	LESS 20% DISCOUNT		-734.00	-298.00
			2,936.00	1,192.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR END PANEL INSULATION SEALANT (SN)	NOT NECESSARY	120.00	-
			160.00	20.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		1,000.00	200.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	200.00
	TUFF COAT.	NOT NECESSARY	200.00	-
	WIRING CHECK.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	NOT NECESSARY	280.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		100.00	50.00
			2,660.00	450.00
	GRAND TOTAL		5,756.00	1,662.00

Report Ref No. CS/INC24080114/Aqh3e2(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,300.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. CS/INC24080114/Aqh3e2(N)

TOTAL FOR SPARE PARTS: \$ 3,096.00 \$ 1,212.00 TOTAL FOR LABOUR: \$ 2,660.00 \$ 450.00 TOTAL REPAIR COST: \$ 5,756.00 \$ 1,662.00

X; Z.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

7

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.