

ESTIMATE

Our Ref: C20240063/TP
Vehicle: YQ913E Mitsubishi Canter
Chassis no.: FEB21EA30097

Date of Loss: 16/07/2024
Insurer: China Taiping
Date of Survey: 12/08/2024

Items	Qty	Nett Items	Amount \$
1	1	Rear tailgate <i>~ X</i>	1,200.00 <i>S/W X</i>
2	1	Rear deck (repair) <i>~ X</i>	200.00 <i>S/W X</i>
3	1	Rear protection beam <i>sent ✓</i>	500.00 <i>S/W ✓</i>
4	1	Rear number plate lamp <i>one ✓</i>	80.00 <i>S/W</i>
5	2	Rear tail lamp @ \$305.00 <i>MSM 2 LS one 1 P C</i>	610.00 <i>S/W</i>
6	2	Rear tail lamp bracket @ \$ <i>RX</i>	<i>X</i>
7	2	Rear stopper @ \$20.00 <i>11 X</i>	40.00 <i>X</i>
Total Parts			2,630.00

Special Nett Items

8	1	Rear number plate with frame <i>sent</i>	30.00 <i>/5</i>
9	1	Rear safety sticker <i>see</i>	60.00 <i>✓</i>
Total Special Nett			90.00

Labour charges

10	To check rear electrical wiring	100.00	20
11	To respray painting and etc	800.00	200
12	Panel beating, cut, weld remove & replacing above parts	800.00	400
Total Labour		<u>1,700.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

4,420.00

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Not Authorised
her
meas
12/8/24
2/5 \$ 1100
2 days*

*P. 758
620
1378
206
1100*