



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO WC 6336D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	TAILLAMPS	SERVICEABLE	\$792.00	\$0.00
2	TAILLAMP BRACKETS	TO REPAIR SEE LABOUR	\$440.00	\$0.00
1	REAR NO. PLATE LAMPS	SERVICEABLE	\$220.00	\$0.00
1	REAR NO. HOLDER	SERVICEABLE	\$198.00	\$0.00
	<b>LESS 15.00% DISCOUNT</b>		(\$247.50)	\$0.00
			\$1,402.50	\$0.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR LH BUCKET / TRAY (SN)	BENT	\$1,600.00	\$700.00
1	SET REAR LH BUCKET / TRAY BRACKETS (SN)	DISTORTED	\$600.00	\$300.00
1	REAR LH BUCKET LOWER BRACKET (SN)	TO REPAIR SEE LABOUR	\$480.00	\$0.00
1	REAR SAFETY BAR (SN) }	BENT	\$3,200.00	\$1,200.00
2	REAR SAFETY BAR SIDE BRACKETS (SN) }	BENT	\$1,200.00	\$0.00
1	REAR NO. PLATE (SN)	SERVICEABLE	\$60.00	\$0.00
1	SET REAR MUDFLAPS (SN)	SERVICEABLE	\$600.00	\$0.00
			\$7,740.00	\$2,200.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REPAIR, REPLACE PARTS, CUTTING WELDING ON REAR ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF TAILLAMP BRACKETS AND REAR LH BUCKET LOWER BRACKET		\$1,200.00	\$600.00
	ANTI RUST		\$150.00	\$50.00
	CHECK WIRING SYSTEM	NOT NECESSARY	\$120.00	\$0.00
	TO DO SPRAY PAINTING ON ACCIDENT AREA		\$800.00	\$450.00
			\$2,270.00	\$1,100.00

<b>GRAND TOTAL</b>	<b>\$11,412.50</b>	<b>\$3,300.00</b>
--------------------	--------------------	-------------------

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>		<b>\$2,600.00</b>
-----------------------------------------------------------------------------	--	-------------------

Report Ref No: CS/FCI24080117/Kqp3

MARKET VALUE: \$36,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$32,474.00=NETT VALUE: \$3,526.00



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.