

QUOTATION FOR REPAIR : FBV3294J

Qty	Description	Repairer's Estimate	
1	BELLY PANEL	220.00	✓
1	FRONT MUDGUARD	200.00	X
1	REAR RHS COVER	230.00	✓
1	RADIATOR COVER	160.00	X
1	BELLY OUTER PANEL RHS	150.00	✓
1	REAR FOOTREST BRACKET	120.00	✓
1	RHS BRAKE LEVER	80.00	✓
1	RHS Z PANEL	260.00	✓
1	EXHAUST COVER	160.00	✓
1	RHS FOOTREST UNDER PANEL	250.00	✓
1	FRONT RIM	450.00	X
1	FRONT FORK	400.00	✓
1	FRONT FORK T CLAMP	320.00	X
1	FRONT WINDSHIELD	180.00	X
1	FRONT WINDSHIELD INNER PANEL	160.00	✓
1	FRONT NUMBER PLATE	60.00	2000
1	RHS SIDE MIRROR	80.00	✓
1	BALANCER SET	60.00	X
1	REAR METAL TOP BOX	480.00	✓ 3000
1	FRONT DISC ROTOR	160.00	✓

10?

NOT WITHIN
Pricing B4pain
4 days
8 2712.00

	4,180.00
Total Part :	4,180.00
Nett Items	

Total Nett items :	0.00
Total parts :	4,180.00

Labour Fee

HANDLEBAR ALIGNMENT	120.00	X
CHASSIS ALIGNMENT	500.00	1501
LABOUR FEE	1,200.00	2001

Total Labour Fee:	1,820.00
Total parts and labour charges :	6,000.00
	7 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: