

ASS. REC. BY:

REF:

1621

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Project 8
North Point Bizhub

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 14,500.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBV 3294 J

Yr Regn:

07 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha

Nmax

c.c

155

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

18769

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MH3SG5680PK177677

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F:

110 / 70 R13

R:

130 / 70 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25 / 7 / 24

D.O.I.

7 / 8 / 2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

& als Body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2100 @ 2713.00 Cash

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

QUOTATION FOR REPAIR :FBV3294J

Qty	Description	Repairer's Estimate	
1	BELLY PANEL	nd 220.00	✓
1	FRONT MUDGUARD	h 200.00	X
1	REAR RHS COVER	nd 230.00	✓
1	RADIATOR COVER	h 160.00	X
1	BELLY OUTER PANEL RHS	nd/h 150.00	✓
1	REAR FOOTREST BRACKET	nd 120.00	✓
1	RHS BRAKE LEVER	nd 80.00	✓
1	RHS Z PANEL	CPA 260.00	✓
1	EXHAUST COVER	nd 160.00	✓
1	RHS FOOTREST UNDER PANEL	nd/h 250.00	✓
1	FRONT RIM	SVC 450.00	X
1	FRONT FORK	R 400.00	✓
1	FRONT FORK T CLAMP	A 320.00	X
1	FRONT WINDSHIELD	h 180.00	X
1	FRONT WINDSHIELD INNER PANEL	nd 160.00	✓
1	FRONT NUMBER PLATE	MIT 60.00	205A
1	RHS SIDE MIRROR	nd 80.00	✓
1	BALANCER SET	h 60.00	X
1	REAR METAL TOP BOX	nd 480.00	✓ 3005A
1	FRONT DISC ROTOR	W 160.00	✓

107

NOT Withheld
Running B & pair
4 days
@ 2712.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer	4,180.00
Signature:	
Total Part :	4,180.00

Nett items

Total Nett items :	0.00
Total parts :	4,180.00

Labour Fee

HANDLEBAR ALIGNMENT	na 120.00	X
CHASSIS ALIGNMENT	500.00	1501
LABOUR FEE	1,200.00	2001

Total Labour Fee:	1,820.00
Total parts and labour charges :	6,000.00

7 DAYS