

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24080119/UPA3Q2**Date:** 15/01/2026**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_05
Claimant Vehicle No : SNR3258T **Insured Vehicle No :** SNF546U
 Date of Loss: 04/08/2024 Nature of Claim: TP Claim No: MFL2024D0008991

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNR3258T**
 Make & Model: HONDA STEPWAGON, 2.0 SPADA E:HEV (A) Engine No: LFA2240816
 Reg. Date: 07/06/2024 (Man. Year: 2024) Chassis No: RP81050839
 Colour: White Odometer: 7462 km
 Engine Capacity: 1993 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm
 Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,828.10	4,497.12	3,330.98	42.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	1,010.00	3,340.00	76.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,178.10	5,507.12	6,670.98	54.78
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	12,178.10	4,400.00	7,778.10	63.87
+ GST 9.00/9.00% (S\$)	1,096.03	396.00	700.03	63.87
Nett Amount (S\$)	13,274.13	4,796.00	8,478.13	63.87
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
(S\$)		5,276.00		
Liabile Amount (50.00%) (S\$)		2,638.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,640.18		
Global Sum Settlement (S\$)		2,640.00		

INSPECTION

Date of Assignment: 15/08/2024
 Date Inspected: 15/08/2024 Inspected At: Ky Auto Pte Ltd (HQ)
 25 KAKI BUKIT ROAD 4 SYNERGY@KB #05-23
 Singapore 417800
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

We have checked and confirmed that all part prices are correct. The actual work carried out and listed as labour and spray painting is accurate, and the fees charged for labour and spray painting are correct.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2024)	
Parts: M1-MPV	HONDA STEPWAGON 2.0 SPADA E:HEV (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SNR3258T)		
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	1,986.80 F	*1,680.00 FL
2	1		*SET FRONT BUMPER CLIP	Necessary	80.00 F	*40.00 FL
3	1		*FRONT FENDER LH	Dented / Bent	692.50 F	*692.50 FL
4	1		*FRONT BUMPER BRACKET LH	Not Necessary	98.60 F	*- FL
5	1		*FRONT BUMPER RETAINER LH	Not Necessary	95.70 F	*- FL
6	1		*FRONT FENDER LINER LH	Not Necessary	130.00 F	*- FL
7	1		*WHEEL RIM	Repair	1,150.60 F	*- FL
8	1		*FRONT FENDER LINER LH	Not Necessary	155.00 F	*- FL
9	1		*FRONT FENDER LINER CLIP	Not Necessary	80.00 F	*- FL
10	1		*FRONT BUMPER CHROME	Scratched	528.40 F	*528.40 FL
11	1		*FRONT HEADLIGHT LH	Cracked	2,680.50 F	*2,680.50 FL
12	1		*SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,828.10	5,621.40
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,124.28
Total Parts (\$)	7,828.10	4,497.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RENEW FRONT AFFECTED ACCIDENT AREAS	New	2,000.00	300.00
2	TO PUTTY SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS	New	1,500.00	600.00
3	TO REPOSITION & INSTALL SENSOR }	New	300.00	20.00
4	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING }	New	200.00	0.00
5	TO RUST PROOF ACCIDENT AREA	New	150.00	30.00
6	TO CARRY OUT WHEEL ALIGNMENT AND WHEEL BALANCING	New	200.00	60.00
			Gross Labour Cost (\$\$)	1,010.00
			4,350.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >