

# KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

not full  
2/5 # 4400/  
the 2nd. After 3 days  
15-18/24

M (65) 9807 3304 Mr. Yap

F (65)

Email: [kyaautosg@gmail.com](mailto:kyaautosg@gmail.com)

Date: 14/08/2024

DOA: 04/08/2024

Honda Stepwagon - SNR3258T

Damaged Area: Front portion

## Parts / Material :

|                          |          |           |            |
|--------------------------|----------|-----------|------------|
| Front Bumper             | cut/Toin | \$ 1680   | 1,986.80 ✓ |
| 1 set Front Bumper clip  | 1 set    | \$ 40     | 80.00 ✓    |
| Front fender LH          | 20/1921  | \$        | 692.50 ✓   |
| Front bumper bracket LH  | 11       | \$        | 98.60 X    |
| Front bumper Retainer LH | 11       | \$        | 95.70 X    |
| Front Fender Liner LH    | 11       | \$        | 130.00 X   |
| Wheel Rim                | 2 set    | \$        | 1,150.60 X |
| Front Fender Liner LH    | 11       | \$        | 155.00 X   |
| Front Fender Liner clip  | 11       | \$        | 80.00 X    |
| Front bumper chrome      | 1 set    | \$        | 528.40 ✓   |
| Front Headlight LH       | 1 set    | \$        | 2,680.50 ✓ |
|                          |          | Parts: \$ | 7,678.10   |

## Special Net Items :

Sealant 11

Total S/N Parts : \$ 150.00 X  
Total S/N Parts : \$ 150.00

## Labour :

|                                                        |    |              |
|--------------------------------------------------------|----|--------------|
| To Remove & Renew Front Affected Accident Areas        | \$ | 2,000.00 300 |
| To Putty, Spray Paint on Front Affected Accident Areas | \$ | 1,500.00 600 |
| To Re-position & Install Sensor                        | \$ | 300.00 320   |
| To Check & Re-Connect all electrical wiring            | \$ | 200.00 30    |
| To Rust Proof Accident Area                            | \$ | 150.00 60    |
| To carry out wheel alignment and wheel balancing.      | \$ | 200.00       |
| Total Labour :                                         |    | \$ 4,350.00  |

TOTAL PARTS : \$ 7,678.10  
TOTAL S/N PARTS : \$ 150.00  
TOTAL LABOUR : \$ 4,350.00  
TOTAL REPAIR COST : \$ 12,178.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5871-4  
202  
4497.12  
1010  
5607.12  
202  
4405.