

ASS. REC. BY:

REF:

MSG/

CS/MSG24080120/Kvp3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of 01-10 10 Admiralty St

Insured: GBE 5665Z

Policy No. 30003159367

Claims No. 355897

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$ 9000

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBL 3660M

Yr Regn:

09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Yamaha

C.C.

530

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

68481

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TYA S109900 0025042

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

120/70R15

R:

160/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

3

mm

Rear

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/4/24

D.O.I.

12/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Await for PR

27/9

11 Lm & 1800k Cnlw

(red 887.30, 33%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

SIN BOON MOTOR CO.

REG NO: 21272900D

10 ADMIRALTY STREET, NORTHLINK BUILDING

#01-10/11

SINGAPORE 757695

SBMOTOR@SINGNET.COM.SG

DATE 14/06/2024

VEHICLE QUOTATION

FBL3660M - YAMAHA TMAX 530 CVT ABS

ITEM	PC	DESCRIPTION	PRICE
1	1 SET	R/S MIRROR COVER	<i>Ad/bm</i> \$153.00 ✓
2	1	EXHAUST COVER	<i>Ad</i> \$295.00 ✓
3	1	EXHAUST COVER SHORT	<i>cm</i> \$204.00 ✓
4	1	R/S TAIL COVER	<i>cm</i> \$216.00 ✓
5	1	R/S FOOT BOARD	<i>cm</i> \$275.00 ✓
6	1	R/S LOWER COVER	<i>cm</i> \$180.00 ✓
7	1	R/S CENTER COVER	<i>cm</i> \$234.00 ✓
8	1	YAMAHA LOGO	<i>na</i> \$30.00 ✓
9	1	R/S TOP COVER	<i>cm</i> \$210.00 ✓
			\$1,797.00
			LESS 10% \$179.70
			\$1,617.30
10		TOW	<i>(Bill)</i> \$120.00 <i>Ad</i>
11		RE-SPRAY	\$550.00 <i>300l</i>
12		LABOUR CHARGE (NETT)	\$400.00 <i>300l</i>
			\$2,687.30
			GST 9% \$241.86
			\$2,929.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
Kenneth (LKK)
21 Aug @ 1800hr
12/8/24
Review After Spray