

ASS. REC. BY:

REF: MSG/Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of 01-10 10 Admiralty St

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 90000

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Await for PR2719 11 Lm & 18000 Cnlw

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1) Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. SI

: Photos

: Others

TOTAL

Veh No: FBL 3660MYr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: YamahaC.C. 530Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 68481

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JYA S10990000-25042Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 120/70R15R: 160/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 3 mmR/Bal. 4 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 17/4/24D.O.I. 12/8/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

CLS body

The U/C / Chassis frame / Body Structure affected due to collision.

SIN BOON MOTOR CO.

REG NO: 21272900D

10 ADMIRALTY STREET, NORTHLINK BUILDING

#01-10/11

SINGAPORE 757695

SBMOTOR@SINGNET.COM.SG

DATE 14/06/2024

VEHICLE QUOTATION

FBL3660M - YAMAHA TMAX 530 CVT ABS

ITEM	PC	DESCRIPTION	PRICE
1	1 SET	R/S MIRROR COVER	<i>Ad/bm</i> \$153.00 ✓
2	1	EXHAUST COVER	<i>Ad</i> \$295.00 ✓
3	1	EXHAUST COVER SHORT	<i>cm</i> \$204.00 ✓
4	1	R/S TAIL COVER	<i>cm</i> \$216.00 ✓
5	1	R/S FOOT BOARD	<i>cm</i> \$275.00 ✓
6	1	R/S LOWER COVER	<i>cm</i> \$180.00 ✓
7	1	R/S CENTER COVER	<i>cm</i> \$234.00 ✓
8	1	YAMAHA LOGO	<i>Ad</i> \$30.00 ✓
9	1	R/S TOP COVER	<i>cm</i> \$210.00 ✓
			\$1,797.00
			LESS 10% \$179.70
			\$1,617.30
10		TOW	<i>(Bill)</i> \$120.00 <i>Ad</i>
11		RE-SPRAY	\$550.00 <i>300l</i>
12		LABOUR CHARGE (NETT)	\$400.00 <i>300l</i>
			\$2,687.30
			GST 9% \$241.86
			\$2,929.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
Kenneth (GKK)
21 Aug @ 1800hr
12/8/24
Review After Spray