

Date: 18-6-2024
Vehicle No: SKN1616M
Model: Toyota Alphard Hybrid
Chassis: AYH30 - 0154245
Reg.Year:

Not Withair
Runway B4 pain
1 day
82201:58

Third Party Insurer:
Third Party Veh No: 21013MID
Date of Accident: 13/6/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT RH SIDE MIRROR <i>87910-38300</i>	1	<i>2498.30</i>	<i>CM</i> \$2,568.90
2	FRONT RH SIDE MIRROR COVER	1		<i>mir</i> \$197.80
3	FRONT RH DOOR PANEL	1		REPAIR
SUB TOTAL				\$2,766.70
LESS 25%				-\$691.68
PARTS TOTAL				\$2,075.03

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR MOULDING CLIPS	1		<i>nn</i> \$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT RH ACCIDENT AREAS & ETC. \$200.00 *Sc!*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR, FRONT SIDE MIRROR COVER, ETC \$400.00 *Sc!*

TO CHECK WIRING & ELECTRICAL SYSTEM. \$80.00 *201*

LABOUR TOTAL \$680.00

TOTAL \$2,805.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

