

Date: 18-6-2024  
Vehicle No: SKN1616M  
Model: Toyota Alphard Hybrid  
Chassis: AYH30 - 0154245  
Reg.Year:

*NOT Withair*  
*Running B4 pain*  
*1 day*

Third Party Insurer:  
Third Party Veh No: 21013MID  
Date of Accident: 13/6/2024  
Estimator: Loong  
Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT RH SIDE MIRROR	1		CM \$2,568.90
2	FRONT RH SIDE MIRROR COVER	1		mir \$197.80
3	FRONT RH DOOR PANEL	1		REPAIR
SUB TOTAL				\$2,766.70
LESS 25%				-\$691.68
PARTS TOTAL				\$2,075.03

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR MOULDING CLIPS	1		\$50.00
S/N TOTAL				\$50.00

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT RH ACCIDENT AREAS & ETC.

\$200.00 *80%*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR, FRONT SIDE MIRROR COVER, ETC

\$400.00 *80%*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 *20%*

LABOUR TOTAL \$680.00

**TOTAL \$2,805.03**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

#### Head office

8 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 0919 | Fax: (+65) 6481 1003

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

